


# ELECTRICAL SAFETY RECALL

## HiKOKI Multi Port Charger

Model UC18YTSL



Double insulation mark

### IDENTIFICATION:

Model UC18YTSL marked with **double insulation mark** on the name plate sold nationally through retailers from 12 August 2019 to 2 December 2019. Other batches not affected.

### DEFECT:

The battery charger does not comply with the relevant mandatory electrical standard. There is no earth cable inside the power cord and some products may not have been earthed correctly.

### HAZARD:

Risk of electric shock which can cause serious injury or death.

### ACTION REQUIRED:

Consumers should immediately stop using the charger and check the double insulation mark to identify if charger is a recalled product. Return affected product to place of purchase or your nearest reseller or HiKOKI Power Tools Australia for a refund or replacement cable fitted.

### For further information

Please direct all calls and any queries concerning this recall to:  
**HiKOKI Power Tools Australia Pty Ltd on 1300 444 822 or email**  
**[enquiry@hikokipowertools.com.au](mailto:enquiry@hikokipowertools.com.au)**

See [www.productsafety.gov.au](http://www.productsafety.gov.au) for Australian product recall information