







## G 3618DA




en Handling instructions

th คู่มือการใช้งาน


**1****2****3****4****5**

6




0

7




0

8




0


9-a




9-b




10




11




12




13



14



15



## GENERAL POWER TOOL SAFETY WARNINGS

### ⚠ WARNING

**Read all safety warnings and all instructions.**

*Failure to follow the warnings and instructions may result in electric shock, fire and/or serious injury.*

**Save all warnings and instructions for future reference.**

*The term "power tool" in the warnings refers to your mains-operated (corded) power tool or battery-operated (cordless) power tool.*

#### 1) Work area safety

- a) **Keep work area clean and well lit.**  
*Cluttered or dark areas invite accidents.*
- b) **Do not operate power tools in explosive atmospheres, such as in the presence of flammable liquids, gases or dust.**  
*Power tools create sparks which may ignite the dust or fumes.*
- c) **Keep children and bystanders away while operating a power tool.**  
*Distractions can cause you to lose control.*

#### 2) Electrical safety

- a) **Power tool plugs must match the outlet. Never modify the plug in any way. Do not use any adapter plugs with earthed (grounded) power tools.**  
*Unmodified plugs and matching outlets will reduce risk of electric shock.*
- b) **Avoid body contact with earthed or grounded surfaces, such as pipes, radiators, ranges and refrigerators.**  
*There is an increased risk of electric shock if your body is earthed or grounded.*
- c) **Do not expose power tools to rain or wet conditions.**  
*Water entering a power tool will increase the risk of electric shock.*
- d) **Do not abuse the cord. Never use the cord for carrying, pulling or unplugging the power tool. Keep cord away from heat, oil, sharp edges or moving parts.**  
*Damaged or entangled cords increase the risk of electric shock.*
- e) **When operating a power tool outdoors, use an extension cord suitable for outdoor use.**  
*Use of a cord suitable for outdoor use reduces the risk of electric shock.*
- f) **If operating a power tool in a damp location is unavoidable, use a residual current device (RCD) protected supply.**  
*Use of an RCD reduces the risk of electric shock.*

#### 3) Personal safety

- a) **Stay alert, watch what you are doing and use common sense when operating a power tool. Do not use a power tool while you are tired or under the influence of drugs, alcohol or medication.**  
*A moment of inattention while operating power tools may result in serious personal injury.*
- b) **Use personal protective equipment. Always wear eye protection.**  
*Protective equipment such as dust mask, non-skid safety shoes, hard hat, or hearing protection used for appropriate conditions will reduce personal injuries.*

- c) **Prevent unintentional starting. Ensure the switch is in the off position before connecting to power source and/or battery pack, picking up or carrying the tool.**

*Carrying power tools with your finger on the switch or energising power tools that have the switch on invites accidents.*

- d) **Remove any adjusting key or wrench before turning the power tool on.**

*A wrench or a key left attached to a rotating part of the power tool may result in personal injury.*

- e) **Do not overreach. Keep proper footing and balance at all times.**

*This enables better control of the power tool in unexpected situations.*

- f) **Dress properly. Do not wear loose clothing or jewellery. Keep your hair, clothing and gloves away from moving parts.**

*Loose clothes, jewellery or long hair can be caught in moving parts.*

- g) **If devices are provided for the connection of dust extraction and collection facilities, ensure these are connected and properly used.**

*Use of dust collection can reduce dust-related hazards.*

#### 4) Power tool use and care

- a) **Do not force the power tool. Use the correct power tool for your application.**

*The correct power tool will do the job better and safer at the rate for which it was designed.*

- b) **Do not use the power tool if the switch does not turn it on and off.**

*Any power tool that cannot be controlled with the switch is dangerous and must be repaired.*

- c) **Disconnect the plug from the power source and/or the battery pack from the power tool before making any adjustments, changing accessories, or storing power tools.**

*Such preventive safety measures reduce the risk of starting the power tool accidentally.*

- d) **Store idle power tools out of the reach of children and do not allow persons unfamiliar with the power tool or these instructions to operate the power tool.**

*Power tools are dangerous in the hands of untrained users.*

- e) **Maintain power tools. Check for misalignment or binding of moving parts, breakage of parts and any other condition that may affect the power tool's operation. If damaged, have the power tool repaired before use.**

*Many accidents are caused by poorly maintained power tools.*

- f) **Keep cutting tools sharp and clean.**

*Properly maintained cutting tools with sharp cutting edges are less likely to bind and are easier to control.*

- g) **Use the power tool, accessories and tool bits etc. in accordance with these instructions, taking into account the working conditions and the work to be performed.**

*Use of the power tool for operations different from those intended could result in a hazardous situation.*

#### 5) Battery tool use and care

- a) **Recharge only with the charger specified by the manufacturer.**

*A charger that is suitable for one type of battery pack may create a risk of fire when used with another battery pack.*

- b) Use power tools only with specifically designated battery packs.  
*Use of any other battery packs may create a risk of injury and fire.*
- c) When battery pack is not in use, keep it away from other metal objects, like paper clips, coins, keys, nails, screws or other small metal objects, that can make a connection from one terminal to another.  
*Shorting the battery terminals together may cause burns or a fire.*
- d) Under abusive conditions, liquid may be ejected from the battery; avoid contact. If contact accidentally occurs, flush with water. If liquid contacts eyes, additionally seek medical help.  
*Liquid ejected from the battery may cause irritation or burns.*
- 6) Service
- a) Have your power tool serviced by a qualified repair person using only identical replacement parts.  
*This will ensure that the safety of the power tool is maintained.*

### PRECAUTION

Keep children and infirm persons away.

When not in use, tools should be stored out of reach of children and infirm persons.

## SAFETY WARNINGS COMMON FOR GRINDING OR ABRASIVE CUTTING-OFF OPERATIONS

- a) This power tool is intended to function as a grinder or cut-off tool. Read all safety warnings, instructions, illustrations and specifications provided with this power tool.  
*Failure to follow all instructions listed below may result in electric shock, fire and/or serious injury.*
- b) Operations such as sanding, wire brushing or polishing are not recommended to be performed with this power tool.  
*Operations for which the power tool was not designed may create a hazard and cause personal injury.*
- c) Do not use accessories which are not specifically designed and recommended by the tool manufacturer.  
*Just because the accessory can be attached to your power tool, it does not assure safe operation.*
- d) The rated speed of the accessory must be at least equal to the maximum speed marked on the power tool.  
*Accessories running faster than their rated speed can break and fly apart.*
- e) The outside diameter and the thickness of your accessory must be within the capacity rating of your power tool.  
*Incorrectly sized accessories cannot be adequately guarded or controlled.*
- f) Threaded mounting of accessories must match the grinder spindle thread. For accessories mounted by flanges, the arbour hole of the accessory must fit the locating diameter of the flange.  
*Accessories that do not match the mounting hardware of the power tool will run out of balance, vibrate excessively and may cause loss of control.*
- g) Do not use a damaged accessory. Before each use inspect the accessory such as abrasive wheels for chips and cracks, backing pad for cracks, tear or excess wear, wire brush for loose or cracked wires. If power tool or accessory is dropped, inspect for damage or install an undamaged accessory. After inspecting and installing an accessory, position yourself and bystanders away from the plane of the rotating accessory and run the power tool at maximum no-load speed for one minute.  
*Damaged accessories will normally break apart during this test time.*
- h) Wear personal protective equipment. Depending on application, use face shield, safety goggles or safety glasses. As appropriate, wear dust mask, hearing protectors, gloves and workshop apron capable of stopping small abrasive or workpiece fragments.  
*The eye protection must be capable of stopping flying debris generated by various operations. The dust mask or respirator must be capable of filtering particles generated by your operation. Prolonged exposure to high intensity noise may cause hearing loss.*
- i) Keep bystanders a safe distance away from work area. Anyone entering the work area must wear personal protective equipment.  
*Fragments of workpiece or of a broken accessory may fly away and cause injury beyond immediate area of operation.*
- j) Hold the power tool by insulated gripping surfaces only, when performing an operation where the cutting tool may contact hidden wiring.  
*Contact with a "live" wire will also make exposed metal parts of the power tool "live" and could give the operator an electric shock.*
- k) Position the cord clear of the spinning accessory.  
*If you lose control, the cord may be cut or snagged and your hand or arm may be pulled into the spinning accessory.*
- l) Never lay the power tool down until the accessory has come to a complete stop.  
*The spinning accessory may grab the surface and pull the power tool out of your control.*
- m) Do not run the power tool while carrying it at your side.  
*Accidental contact with the spinning accessory could snag your clothing, pulling the accessory into your body.*
- n) Regularly clean the power tool's air vents.  
*The motor's fan will draw the dust inside the housing and excessive accumulation of powdered metal may cause electrical hazards.*
- o) Do not operate the power tool near flammable materials.  
*Sparks could ignite these materials.*
- p) Do not use accessories that require liquid coolants.  
*Using water or other liquid coolants may result in electrocution or shock.*

## KICKBACK AND RELATED WARNINGS

Kickback is a sudden reaction to a pinched or snagged rotating wheel, backing pad, brush or any other accessory. Pinching or snagging causes rapid stalling of the rotating accessory which in turn causes the uncontrolled power tool to be forced in the direction opposite of the accessory's rotation at the point of the binding.  
*For example, if an abrasive wheel is snagged or pinched by the workpiece, the edge of the wheel that is entering into the pinch point can dig into the surface of the material causing the wheel to climb out or kick out. The wheel may either jump*

## English

toward or away from the operator, depending on direction of the wheel's movement at the point of pinching.

Abrasive wheels may also break under these conditions.

Kickback is the result of power tool misuse and/or incorrect operating procedures or conditions and can be avoided by taking proper precautions as given below.

- a) **Maintain a firm grip on the power tool and position your body and arm to allow you to resist kickback forces. Always use auxiliary handle, if provided, for maximum control over kickback or torque reaction during start-up.**  
*The operator can control torque reactions or kickback forces, if proper precautions are taken.*
- b) **Never place your hand near the rotating accessory. Accessory may kickback over your hand.**
- c) **Do not position your body in the area where power tool will move if kickback occurs.**  
*Kickback will propel the tool in direction opposite to the wheel's movement at the point of snagging.*
- d) **Use special care when working corners, sharp edges etc. Avoid bouncing and snagging the accessory.**  
*Corners, sharp edges or bouncing have a tendency to snag the rotating accessory and cause loss of control or kickback.*
- e) **Do not attach a saw chain woodcarving blade or toothed saw blade.**  
*Such blades create frequent kickback and loss of control.*

### SAFETY WARNINGS SPECIFIC FOR GRINDING AND ABRASIVE CUTTING-OFF OPERATIONS

- a) **Use only wheel types that are recommended for your power tool and the specific guard designed for the selected wheel.**  
*Wheels for which the power tool was not designed cannot be adequately guarded and are unsafe.*
- b) **The grinding surface of centre depressed wheels must be mounted below the plane of the guard lip.**  
*An improperly mounted wheel that projects through the plane of the guard lip cannot be adequately protected.*
- c) **The guard must be securely attached to the power tool and positioned for maximum safety, so the least amount of wheel is exposed towards the operator.**  
*The guard helps to protect the operator from broken wheel fragments, accidental contact with wheel and sparks that could ignite clothing.*
- d) **Wheels must be used only for recommended applications. For example: do not grind with the side of cut-off wheel.**  
*Abrasive cut-off wheels are intended for peripheral grinding, side forces applied to these wheels may cause them to shatter.*
- e) **Always use undamaged wheel flanges that are of correct size and shape for your selected wheel.**  
*Proper wheel flanges support the wheel thus reducing the possibility of wheel breakage. Flanges for cut-off wheels may be different from grinding wheel flanges.*
- f) **Do not use worn down wheels from larger power tools.**  
*Wheel intended for larger power tool is not suitable for the higher speed of a smaller tool and may burst.*

### ADDITIONAL SAFETY WARNINGS SPECIFIC FOR ABRASIVE CUTTING-OFF OPERATIONS

- a) **Do not "jam" the cut-off wheel or apply excessive pressure. Do not attempt to make an excessive depth of cut.**  
*Overstressing the wheel increases the loading and susceptibility to twisting or binding of the wheel in the cut and the possibility of kickback or wheel breakage.*
- b) **Do not position your body in line with and behind the rotating wheel.**  
*When the wheel, at the point of operation, is moving away from your body, the possible kickback may propel the spinning wheel and the power tool directly at you.*
- c) **When wheel is binding or when interrupting a cut for any reason, switch off the power tool and hold the power tool motionless until the wheel comes to a complete stop. Never attempt to remove the cut-off wheel from the cut while the wheel is in motion otherwise kickback may occur.**  
*Investigate and take corrective action to eliminate the cause of wheel binding.*
- d) **Do not restart the cutting operation in the workpiece. Let the wheel reach full speed and carefully re-enter the cut.**  
*The wheel may bind, walk up or kickback if the power tool is restarted in the workpiece.*
- e) **Support panels or any oversized workpiece to minimize the risk of wheel pinching and kickback.**  
*Large workpieces tend to sag under their own weight. Supports must be placed under the workpiece near the line of cut and near the edge of the workpiece on both sides of the wheel.*
- f) **Use extra caution when making a "pocket cut" into existing walls or other blind areas.**  
*The protruding wheel may cut gas or water pipes, electrical wiring or objects that can cause kickback.*

### GENERAL SAFETY INSTRUCTIONS FOR CORDLESS DISC GRINDERS

- Check that speed marked on the wheel is equal to or greater than the rated speed of the grinder;
- Ensure that the wheel dimensions are compatible with the grinder;
- Abrasive wheels shall be stored and handled with care in accordance with manufacturer's instructions;
- Inspect the grinding wheel before use, do not use chipped, cracked or otherwise defective products;
- Ensure that mounted wheels and points are fitted in accordance with the manufacturer's instructions;
- Ensure that blotters are used when they are provided with the bonded abrasive product and when they are required;
- Ensure that the abrasive product is correctly mounted and tightened before use and run the tool at no-load for 30 seconds in a safe position, stop immediately if there is considerable vibration or if other defects are detected. If this condition occurs, check the machine to determine the cause;
- If a guard is equipped with the tool never use the tool without such a guard;
- When using a abrasive cutting wheel, be sure to remove the standard accessory wheel guard and attach the wheel guard with side guard (sold separately) (Fig. 5);
- Do not use separate reducing bushings or adapters to adapt large hole abrasive wheels;
- For tools intended to be fitted with threaded hole wheel, ensure that the thread in the wheel is long enough to accept the spindle length;

- Check that the work piece is properly supported;
- Do not use cutting off wheel for side grinding;
- Ensure that sparks resulting from use do not create a hazard e.g. do not hit persons, or ignite flammable substances;
- Ensure that ventilation openings are kept clear when working in dusty conditions, if it should become necessary to clear dust, first disconnect the tool from the mains supply (use non metallic objects) and avoid damaging internal parts;
- Always use eye and ear protection. Other personal protective equipment such as dust mask, gloves, helmet and apron should be worn;
- Pay attention to the wheel that continues to rotate after the tool is switched off.
- Do not allow foreign matter to enter the hole for connecting the rechargeable battery.
- Never disassemble the rechargeable battery and charger.
- Never short-circuit the rechargeable battery. Shortcircuiting the battery will cause a great electric current and overheat. It results in burn or damage to the battery.
- Do not dispose of the battery in fire. If the battery is burnt, it may explode.
- Do not insert object into the air ventilation slots of the charger. Inserting metal objects or inflammables into the charger air ventilation slots will result in electrical shock hazard or damaged charger.
- Bring the battery to the shop from which it was purchased as soon as the post-charging battery life becomes too short for practical use. Do not dispose of the exhausted battery.

9. Keep the tool's terminals (battery mount) free of swarf and dust.
  - Prior to use, make sure that swarf and dust have not collected in the area of the terminals.
  - During use, try to avoid swarf or dust on the tool from falling on the battery.
  - When suspending operation or after use, do not leave the tool in an area where it may be exposed to falling swarf or dust.  
Doing so could cause a short circuit that could result in smoke emission or ignition.

## PRECAUTIONS FOR BATTERY AND CHARGER

1. Always charge the battery at an ambient temperature of -10–40°C. A temperature of less than -10°C will result in over charging which is dangerous. The battery cannot be charged at a temperature greater than 40°C. The most suitable temperature for charging is that of 20–25°C.
2. Do not use the charger continuously. When one charging is completed, leave the charger for about 15 minutes before the next charging of battery.
3. Do not allow foreign matter to enter the hole for connecting the rechargeable battery.
4. Never disassemble the rechargeable battery or charger.
5. Never short-circuit the rechargeable battery. Short-circuiting the battery will cause a great electric current and overheat. It results in burn or damage to the battery.
6. Do not dispose of the battery in fire. If the battery is burnt, it may explode.
7. Using an exhausted battery will damage the charger.
8. Bring the battery to the shop from which it was purchased as soon as the post-charging battery life becomes too short for practical use. Do not dispose of the exhausted battery.
9. Do not insert objects into the air ventilation slots of the charger. Inserting metal objects or flammable into the charger air ventilation slots will result in an electrical shock hazard or damage to the charger.

## ADDITIONAL SAFETY WARNINGS

1. Ensure that the depressed center wheel to be utilized is the correct type and free of cracks or surface defects. Also ensure that the depressed center wheel is properly mounted and the wheel nut is securely tightened.
2. Confirm that the push button is disengaged by pushing push button two or three times before switching the power tool on.
3. To prolong the life of the machine and ensure a first class finish, it is important that the machine should not be overloaded by applying too much pressure. In most applications, the weight of the machine alone is sufficient for effective grinding. Too much pressure will result in reduced rotational speed, inferior surface finish, and overloading which could reduce the life of the machine.
4. The wheel continues to rotate after the tool is switched off.  
After switching off the machine, do not put it down until the depressed center wheel has come to a complete stop. Apart from avoiding serious accidents, this precaution will reduce the amount of dust and swarf sucked into the machine.
5. When the machine is not use, the power source should be disconnected.
6. Be sure to switch OFF and disconnect the attachment plug from the receptacle to avoid a serious accident before the depressed center wheel is assembling and disassembling.
7. Be careful of brake kickback.  
This cordless disc grinder features an electric brake that functions when the switch is released. As there is some kickback when the brake functions, be sure to hold the main body securely.
8. Do not use the product if the tool or the battery terminals (battery mount) are deformed.  
Installing the battery could cause a short circuit that could result in smoke emission or ignition.

## CAUTION ON LITHIUM-ION BATTERY

To extend the lifetime, the lithium-ion battery equips with the protection function to stop the output.

In the cases of 1 to 3 described below, when using this product, even if you are pulling the switch, the motor may stop. This is not the trouble but the result of protection function.

1. When the battery power remaining runs out, the motor stops.  
In such a case, charge it up immediately.
2. If the tool is overloaded, the motor may stop. In this case, release the switch of tool and eliminate causes of overloading. After that, you can use it again.
3. If the battery is overheated under overload work, the battery power may stop.  
In this case, stop using the battery and let the battery cool. After that, you can use it again.

Furthermore, please heed the following warning and caution.

### WARNING

In order to prevent any battery leakage, heat generation, smoke emission, explosion and ignition beforehand, please be sure to heed the following precautions.

1. Make sure that swarf and dust do not collect on the battery.
- During work make sure that swarf and dust do not fall on the battery.

## English

- Make sure that any swarf and dust falling on the power tool during work do not collect on the battery.
- Do not store an unused battery in a location exposed to swarf and dust.
- Before storing a battery, remove any swarf and dust that may adhere to it and do not store it together with metal parts (screws, nails, etc.).
- 2. Do not pierce battery with a sharp object such as a nail, strike with a hammer, step on, throw or subject the battery to severe physical shock.
- 3. Do not use an apparently damaged or deformed battery.
- 4. Do not use the battery in reverse polarity.
- 5. Do not connect directly to an electrical outlets or car cigarette lighter sockets.
- 6. Do not use the battery for a purpose other than those specified.
- 7. If the battery charging fails to complete even when a specified recharging time has elapsed, immediately stop further recharging.
- 8. Do not put or subject the battery to high temperatures or high pressure such as into a microwave oven, dryer, or high pressure container.
- 9. Keep away from fire immediately when leakage or foul odor are detected.
- 10. Do not use in a location where strong static electricity generates.
- 11. If there is battery leakage, foul odor, heat generated, discolored or deformed, or in any way appears abnormal during use, recharging or storage, immediately remove it from the equipment or battery charger, and stop use.
- 12. Do not immerse the battery or allow any fluids to flow inside. Conductive liquid ingress, such as water, can cause damage resulting in fire or explosion. Store your battery in a cool, dry place, away from combustible and flammable items. Corrosive gas atmospheres must be avoided.

### CAUTION

1. If liquid leaking from the battery gets into your eyes, do not rub your eyes and wash them well with fresh clean water such as tap water and contact a doctor immediately.  
If left untreated, the liquid may cause eye-problems.
2. If liquid leaks onto your skin or clothes, wash well with clean water such as tap water immediately.  
There is a possibility that this can cause skin irritation.
3. If you find rust, foul odor, overheating, discolor, deformation, and/or other irregularities when using the battery for the first time, do not use and return it to your supplier or vendor.

### WARNING

If a conductive foreign matter enters in the terminal of lithium ion battery, the battery may be shorted, causing fire. When storing the lithium ion battery, obey surely the rules of following contents.

- Do not place conductive debris, nail and wires such as iron wire and copper wire in the storage case.
- To prevent shorting from occurring, load the battery in the tool or insert securely the battery cover for storing until the ventilator is not seen.


## REGARDING LITHIUM-ION BATTERY TRANSPORTATION

When transporting a lithium-ion battery, please observe the following precautions.

### WARNING

Notify the transporting company that a package contains a lithium-ion battery, inform the company of its power output and follow the instructions of the transportation company when arranging transport.

- Lithium-ion batteries that exceed a power output of 100 Wh are considered to be in the freight classification of Dangerous Goods and will require special application procedures.
- For transportation abroad, you must comply with international law and the rules and regulations of the destination country.
- If the BSL36B18 is installed in the power tool, the power output will exceed 100 Wh and the unit will be classified as Dangerous Goods for freight classification.



## USB DEVICE CONNECTION PRECAUTIONS (UC18YSL3)

When an unexpected problem occurs, the data in a USB device connected to this product may be corrupted or lost. Always make sure to back up any data contained in the USB device prior to use with this product.

Please be aware that our company accepts absolutely no responsibility for any data stored in a USB device that is corrupted or lost, nor for any damage that may occur to a connected device.

### WARNING

- Prior to use, check the connecting USB cable for any defect or damage.  
Using a defective or damaged USB cable can cause smoke emission or ignition.
- When the product is not being used, cover the USB port with the rubber cover.  
Buildup of dust etc. in the USB port can cause smoke emission or ignition.

### NOTE

- There may be an occasional pause during USB recharging.
- When a USB device is not being charged, remove the USB device from the charger.  
Failure to do so may not only reduce the battery life of a USB device, but may also result in unexpected accidents.
- It may not be possible to charge some USB devices, depending on the type of device.

## NAMES OF PARTS (Fig. 1–Fig. 15)

①	Motor	⑩	Battery level indicator switch
②	Nameplate	⑪	Battery level indicator lamp
③	Lock pin	⑫	Lever
④	Side handle	⑬	Hex. bar wrench
⑤	Gear cover	⑭	Wheel washer (E)
⑥	Depressed center wheel	⑮	Wheel nut
⑦	M5 hex. socket bolt	⑯	Wrench
⑧	Wheel guard	⑰	With side guard
⑨	Filter	⑱	Abrasive cutting wheel
⑩	Switch lock	⑲	Lock lever
⑪	Switch	⑳	Mode indicator lamp
⑫	Auto mode indicator switch	㉑	Rubber cover
⑬	Battery	㉒	USB port
⑭	Latch	㉓	USB cable
⑮	Charge indicator lamp		

	Remaining battery indicator switch
--	------------------------------------

## Battery

	Lights ; The battery remaining power is over 75%
	Lights ; The battery remaining power is 50%–75%.
	Lights ; The battery remaining power is 25%–50%.
	Lights ; The battery remaining power is less than 25%
	Blinks ; The battery remaining power is nearly empty. Recharge the battery soonest possible.
	Blinks ; Output suspended due to high temperature. Remove the battery from the tool and allow it to fully cool down.
	Blinks ; Output suspended due to failure or malfunction. The problem may be the battery so please contact your dealer.

## STANDARD ACCESSORIES

In addition to the main unit (1 unit), the package contains the accessories listed on page 29.

Standard accessories are subject to change without notice.

## SYMBOLS

### WARNING

The following show symbols used for the machine.  
Be sure that you understand their meaning before use.

	G3618DA: Cordless Disc Grinder
	To reduce the risk of injury, user must read instruction manual.
	Always wear eye protection.
V	Rated voltage
n	Rated speed
n <sub>0</sub>	No-load rotation speed
/min	Revolution or reciprocations per minute
	Switching ON
	Switching OFF
Lock 	Switching locks to the "ON" position
	Disconnect the battery
	Warning

## APPLICATIONS

- Removal of casting fin and finishing of various types of steel, bronze and aluminum materials and castings.
- Grinding of welded sections or sections cut by means of a cutting wheel.
- Grinding of synthetic resins, slate, brick, marble, etc.

## SPECIFICATIONS

### 1. Power tool

		Model	G3618DA
Voltage		36 V	
Rated speed		5300 /min Auto mode: 3200 /min	
Wheel	Outer dia.	180 mm	
	Hole dia.	22.23 mm	
	Thickness	6 mm	
Peripheral speed		80 m/s	
Battery available for this tool*		BSL36B18	
Weight		4.7 kg	

\* Existing batteries (BSL3660/3620/3626, BSL18xx series, etc.) and AC/DC adapter (ET36A) cannot be used with this tool.

### NOTE

Due to HiKOKI's continuing program of research and development, the specifications herein are subject to change without prior notice.

# English

## Electronic control

- Soft start  
Reduces recoil against the operator by managing the number of rotations during startup.
- Braking Function  
Brake is activated when the switch is turned off, stopping the motor's rotation.
- Overload protection  
This protection feature cuts off the power to the motor in the event of overloading of motor or a conspicuous reduction in rotational speed during operation. When the overload protection feature has been activated, the motor may stop. In this case, release the tool switch and eliminate causes of overloading. After that you can use it again.
- Overheat protection  
This protection feature cuts off the power to the motor and stops the power tool in the event of overheating of motor during operation. When the overheat protection feature has been activated, the motor may stop. In this case, release the tool switch and cool it down in a few minutes. After that you can use it again.
- Restart prevention function  
When the power is still switched on, the tool will not restart when a battery is installed. This function can be canceled once the tool is switched off.

## 2. Battery

Model	BSL36B18
Voltage	36 V / 18 V (Automatic Switching*)
Battery capacity	4.0 Ah / 8.0 Ah (Automatic Switching*)
Available cordless products**	Multi volt series, 18V product
Available charger	Sliding charger for lithium ion batteries

\* The tool itself will automatically switch over.

\*\* Please see our general catalogue for details.

## 3. Charger

Model	UC18YSL3
Charging voltage	14.4 V-18 V
Weight	0.6 kg

## CHARGING

Before using the power tool, charge the battery as follows.

1. **Connect the charger's power cord to the receptacle.**  
When connecting the plug of the charger to a receptacle, the charge indicator lamp will blink in red (At 1- second intervals).
2. **Insert the battery into the charger.**  
Firmly insert the battery into the charger as shown in **Fig. 3** (on page 2).
3. **Charging**  
When inserting a battery in the charger, the charge indicator lamp will blink in blue.  
When the battery becomes fully recharged, the charge indicator lamp will light up in green. (See **Table 1**)
  - (1) Charge indicator lamp indication  
The indications of the charge indicator lamp will be as shown in **Table 1**, according to the condition of the charger or the rechargeable battery.

**Table 1**

Indications of the charge indicator lamp				
Charge indicator lamp (RED / BLUE / GREEN / PURPLE)	Before charging	Blinks (RED)	Lights for 0.5 seconds. Does not light for 0.5 seconds. (off for 0.5 seconds)	Plugged into power source
	While charging	Blinks (BLUE)	Lights for 0.5 seconds. Does not light for 1 second. (off for 1 second)	Battery capacity at less than 50%
		Blinks (BLUE)	Lights for 1 second. Does not light for 0.5 seconds. (off for 0.5 seconds)	Battery capacity at less than 80%
		Lights (BLUE)	Lights continuously	Battery capacity at more than 80%
	Charging complete	Lights (GREEN)	Lights continuously (Continuous buzzer sound: about 6 seconds)	
	Overheat standby	Blinks (RED)	Lights for 0.3 seconds. Does not light for 0.3 seconds. (off for 0.3 seconds)	Battery overheated. Unable to charge. (Charging will commence when battery cools)
	Charging impossible	Flickers (PURPLE)	Lights for 0.1 seconds. Does not light for 0.1 seconds. (Intermittent buzzer sound: about 2 seconds)	Malfunction in the battery or the charger

- (2) Regarding the temperatures and charging time of the rechargeable battery  
The temperatures and charging time will become as shown in **Table 2**.

**Table 2**

Charger		UC18YSL3					
Battery	Type of battery	Li-ion					
	Temperatures at which the battery can be recharged	0°C–50°C					
	Charging voltage	V	14.4		18		
	Charging time, approx. (At 20°C)	min	BSL14xx series		BSL18xx series		Multi volt series
			(4 cells)	(8 cells)	(5 cells)	(10 cells)	(10 cells)
		BSL1415S : 15 BSL1415 : 15 BSL1415X : 15 BSL1420 : 20 BSL1425 : 25 BSL1430C : 30	BSL1430 : 20 BSL1440 : 26 BSL1450 : 32 BSL1460 : 38	BSL1815S : 15 BSL1815 : 15 BSL1815X : 15 BSL1820 : 20 BSL1825 : 25 BSL1830C : 30 BSL1850C : 32	BSL1830 : 20 BSL1840 : 26 BSL1850 : 32 BSL1860 : 38	BSL36A18 : 32 BSL36B18 : 52	
USB	Charging voltage	V	5				
	Charging current	A	2				

**NOTE**

The recharging time may vary according to the ambient temperature and power source voltage.

4. **Disconnect the charger’s power cord from the receptacle.**

5. **Hold the charger firmly and pull out the battery.**

**NOTE**

Be sure to pull out the battery from the charger after use, and then keep it.

- When the charge indicator lamp flickers (at 0.2-second intervals), check for and take out any foreign objects in the charger’s battery connector. If there are no foreign objects, it is probable that the battery or charger is malfunctioning. Take it to your authorized Service Center.
- Since the built-in micro computer takes about 3 seconds to confirm that the battery being charged with UC18YSL3 is taken out, wait for a minimum of 3 seconds before reinserting it to continue charging. If the battery is reinserted within 3 seconds, the battery may not be properly charged.

**Regarding electric discharge in case of new batteries, etc.**

As the internal chemical substance of new batteries and batteries that have not been used for an extended period is not activated, the electric discharge might be low when using them the first and second time. This is a temporary phenomenon, and normal time required for recharging will be restored by recharging the batteries 2–3 times.

**How to make the batteries perform longer.**

- (1) Recharge the batteries before they become completely exhausted.  
When you feel that the power of the tool becomes weaker, stop using the tool and recharge its battery. If you continue to use the tool and exhaust the electric current, the battery may be damaged and its life will become shorter.
- (2) Avoid recharging at high temperatures.  
A rechargeable battery will be hot immediately after use. If such a battery is recharged immediately after use, its internal chemical substance will deteriorate, and the battery life will be shortened. Leave the battery and recharge it after it has cooled for a while.

**CAUTION**

- If the battery is charged while it is heated because it has been left for a long time in a location subject to direct sunlight or because the battery has just been used, the charge indicator lamp of the charger lights for 0.3 seconds, does not light for 0.3 seconds (off for 0.3 seconds). In such a case, first let the battery cool, then start charging.

## MOUNTING AND OPERATION

Action	Figure	Page
Removing and inserting the battery	2	2
Charging	3	2
Remaining battery indicator	4	2
Fitting and adjusting the wheel guard	5	2
Fixing the side handle	6	3
Assembling depressed center wheel*1	7	3
Assembling cutting wheel*1	8	3
Switch operation	9-a	4
Switch operation (with Lock-on)*2	9-b	4
Adjusting the number of revolution*3	10	4
Grinding angle and grinding method	11	4
Detaching the filter	12	5
Charging a USB device from an electrical outlet	13-a	5

# English

Charging a USB device and battery from a electrical outlet	13-b	5
How to recharge USB device	14	5
When charging of USB device is completed	15	5
Selecting accessories	—	30

## \*1 WARNING

Before use, be sure to tighten the wheel nut with the included wrench.

Failure to tighten could result in the wheel nut loosening when the brake is activated during a stop.

## NOTE

The wheel washer is specifically for this product. Do not use it for any other product.

\*2 Subject to change depending on area.

## \*3 About the Mode change function and Mode display lamp

With the storage battery installed to the main unit and the unit switched on, pressing the Mode Change switch will switch the operation mode to auto mode. While in Auto Mode, the Mode display lamp will remain lit.

- With Auto Mode, you can lower noise and vibration by lowering the maximum number of revolutions while in a no-load state.

While in Auto Mode, the number of revolutions will be raised if the load becomes greater during operation.

On the other hand, the number of revolutions will be lowered if the load decreases during operation.

- This product features a protection function. When the protection function mentioned below is activated, the mode display lamp will flash.

[Overload Protection Function]

Operation is stopped because of an overload.

Try operating the unit once again when the cause of the overload has been removed.

[Temperature Protection Function]

Operation is stopped because the unit is overheated.

Cool the unit in a location that is shaded and well-ventilated.

Try operating the unit once again after it has sufficiently cooled.

## MAINTENANCE AND INSPECTION

### 1. Inspecting the depressed center wheel

Ensure that the depressed center wheel is free of cracks and surface defects.

### 2. Inspecting the mounting screws

Regularly inspect all mounting screws and ensure that they are properly tightened. Should any of the screws be loose, retighten them immediately. Failure to do so could result in serious hazard.

### 3. Maintenance of the motor

The motor unit winding is the very "heart" of the power tool. Exercise due care to ensure the winding does not become damaged and/or wet with oil or water.

### 4. Inspection of terminals (tool and battery)

Check to make sure that swarf and dust have not collected on the terminals.

On occasion check prior, during and after operation.

## CAUTION

Remove any swarf or dust which may have collected on the terminals.

Failure to do so may result in malfunction.

## 5. Cleaning on the outside

When the cordless disc grinder is stained, wipe with a soft dry cloth or a cloth moistened with soapy water. Do not use chloric solvents, gasoline or paint thinner, for they melt plastics.

## 6. Cleaning the filter

After use, detach the filter and remove any grime or dust from the screen with an airgun or other tool. (Fig. 12)

## NOTE

- To clear the unit of grime or dust, periodically run the motor in a no-load state and blow dry air into the ventilation hole with the filter removed.

Accumulation of grime or dust accumulates in the motor can cause damage.

- After cleaning, make sure to securely attach the filter.

## 7. Storage

Store the cordless disc grinder in a place in which the temperature is less than 40°C, and out of reach of children.

## NOTE

Storing lithium-ion batteries.

Make sure the lithium-ion batteries have been fully charged before storing them.

Prolonged storage (3 months or more) of batteries with a low charge may result in performance deterioration, significantly reducing battery usage time or rendering the batteries incapable of holding a charge.

However, significantly reduced battery usage time may be recovered by repeatedly charging and using the batteries two to five times.

If the battery usage time is extremely short despite repeated charging and use, consider the batteries dead and purchase new batteries.

## CAUTION

In the operation and maintenance of power tools, the safety regulations and standards prescribed in each country must be observed.

### Important notice on the batteries for the HIKOKI cordless power tools

Please always use one of our designated genuine batteries. We cannot guarantee the safety and performance of our cordless power tool when used with batteries other than these designated by us, or when the battery is disassembled and modified (such as disassembly and replacement of cells or other internal parts).

## NOTE

Due to HIKOKI's continuing program of research and development, the specifications herein are subject to change without prior notice.

## TROUBLESHOOTING

Use the inspections in the table below if the tool does not operate normally. If this does not remedy the problem, consult your dealer or the HIKOKI Authorized Service Center.

### 1. Power tool

Symptom	Possible cause	Remedy
Tool doesn't run	No remaining battery power	Charge the battery.
	Battery isn't fully installed.	Push the battery in until you hear a click.
	Foreign matter is keeping the lock pin pressed down.	Remove the foreign matter from the lock pin.
	The battery is installed while the switch is turned ON.	Turn the switch OFF and then ON again.
Tool suddenly stopped	Tool was overburdened	Get rid of the problem causing the overburden.
	Overload protection is in operation.	
	The battery is overheated.	Let the battery cool down.
Abnormal noise. Grinding wheel shakes	Wheel nut is loose.	Fully tighten the wheel nut.
	The wheel nut, wheel rusher, grinding wheel, etc. are improperly installed facing the wrong direction.	Check the installed direction and correctly install the parts.
	Foreign matter is caught between the wheel nut, wheel washer, grinding wheel, etc.	Remove the foreign matter.
Brake doesn't operate properly.	Main unit may be at fault.	Immediately discontinue use and contact your dealer for repairs.
Battery cannot be installed	Attempting to install a battery other than that specified for the tool.	Please install a multi volt type battery.

### 2. Charger

Symptom	Possible cause	Remedy
The charge indicator lamp rapidly flickers purple, and battery charging doesn't begin.	The battery is not inserted all the way.	Insert the battery firmly.
	There is foreign matter in the battery terminal or where the battery is attached.	Remove the foreign matter.
The charge indicator lamp blinks red, and battery charging doesn't begin.	The battery is not inserted all the way.	Insert the battery firmly.
	The battery is overheated.	If left alone, the battery will automatically begin charging if its temperature decreases, but this may reduce battery life. It is recommended that the battery be cooled in a well-ventilated location away from direct sunlight before charging it.
Battery usage time is short even though the battery is fully charged.	The battery's life is depleted.	Replace the battery with a new one.
The battery takes a long time to charge.	The temperature of the battery, the charger, or the surrounding environment is extremely low.	Charge the battery indoors or in another warmer environment.
	The charger's vents are blocked, causing its internal components to overheat.	Avoid blocking the vents.
	The cooling fan is not running.	Contact a HIKOKI Authorized Service Center for repairs.
The USB power lamp has switched off and the USB device has stopped charging.	The battery's capacity has become low.	Replace the battery with one that has capacity remaining.
		Plug the charger's power plug into an electric socket.

## English

Symptom	Possible cause	Remedy
USB power lamp does not switch off even though the USB device has finished charging.	The USB power lamp lights up green to indicate that USB charging is possible.	This is not a malfunction.
It is unclear what the charging status of a USB device is, or whether its charging is complete.	The USB power lamp does not switch off even when charging is complete.	Examine the USB device that is charging to confirm its charging status.
Charging of a USB device pauses midway.	The charger was plugged into an electrical socket while the USB device was being charged using the battery as the power source.	This is not a malfunction. The charger pauses USB charging for about 5 seconds when it is differentiating between power sources.
	A battery was inserted into the charger while the USB device was being charged using a power socket as the power source.	
Charging of the USB device pauses midway when the battery and the USB device are being charged at the same time.	The battery has become fully charged.	This is not a malfunction. The charger pauses USB charging for about 5 seconds while it checks whether the battery has successfully completed charging.
Charging of the USB device doesn't start when the battery and the USB device are being charged at the same time.	The remaining battery capacity is extremely low.	This is not a malfunction. When the battery capacity reaches a certain level, USB charging automatically begins.

## กฎความปลอดภัยโดยทั่วไป

### คำเตือน

โปรดอ่านคำเตือนเพื่อความปลอดภัยและคำแนะนำทั้งหมด

การไม่ปฏิบัติตามคำเตือนและคำแนะนำ อาจทำให้เกิดไฟฟ้าช็อต เกิดไฟไหม้ และ/หรือการบาดเจ็บสาหัสได้

บันทึกคำเตือนและคำแนะนำไว้สำหรับใช้อ้างอิงในอนาคต

คำว่า “เครื่องมือกล” ในคำเตือนนี้ หมายถึงเครื่องมือกลที่ใช้ร่วมกับปลั๊กไฟฟ้า (มีสายไฟ) หรือใช้งานกับแบตเตอรี่ (ไร้สาย)

#### 1) พื้นที่ทำงานอย่างปลอดภัย

- รักษาพื้นที่ทำงานให้สะอาดและมีแสงสว่างเพียงพอ  
สิ่งของที่เกะกะหรือพื้นที่ที่มีสิ่งของน่ามาซึ่งอุบัติเหตุ
- อย่าใช้เครื่องมือไฟฟ้าในบรรยากาศที่อาจระเบิด เช่น มี  
ของเหลวไวไฟ แก๊สหรือฝุ่น  
เครื่องมือไฟฟ้าอาจเกิดประกายไฟที่อาจทำให้ฝุ่นและไอติดไฟ  
ได้
- ใช้งานเครื่องมือไฟฟ้าให้ไกลจากเด็กและคนเฝ้าชม  
คนที่วอกแวกทำให้คุณขาดสมาธิในการทำงานได้

#### 2) ความปลอดภัยทางไฟฟ้า

- ปลั๊กของเครื่องมือไฟฟ้าต้องเหมาะกับเต้าเสียบ  
อย่าตัดแปลงปลั๊ก  
อย่าใช้ปลั๊กของตัวปรับแรงดันไฟฟ้ากับเครื่องมือไฟฟ้าชนิดที่  
ต่อลงดิน  
ปลั๊กกันดูดเสียบที่ไม่พอดีกันอาจทำให้คุณถูกไฟฟ้าดูด
- อย่าให้ตัวคุณสัมผัสกับพื้นผิวที่ต่อลงดิน เช่นท่อโลหะ  
เครื่องทำความร้อน เต้าอบ ตู้เย็น เป็นต้น  
อาจถูกไฟฟ้าดูดถ้าร่างกายของคุณต้องจรลงดิน
- อย่าให้เครื่องมือไฟฟ้าถูกกับน้ำฝนหรือความเปียกชื้น  
น้ำที่เข้าไปในเครื่องมือไฟฟ้าจะเพิ่มความเสี่ยงที่จะถูกไฟฟ้าดูด
- อย่าใช้สายไฟฟ้าในงานอื่น อย่าใช้สายเพื่อหิ้ว ดึงหรือ เสียบ  
เครื่องมือไฟฟ้า ให้สายไฟอยู่ห่างจากความร้อน น้ำมัน  
ขอบแหลมคมหรือชิ้นส่วนที่เคลื่อนไหว  
สายที่ชำรุดหรือดึงอาจทำให้คุณถูกไฟฟ้าดูดได้ง่าย
- เมื่อใช้งานเครื่องมือไฟฟ้านอกอาคาร  
ใช้สายพ่วงชนิดที่ใช้กับนอกอาคารเมื่อใช้สายที่เหมาะสมจะลด  
ความเสี่ยงที่จะถูกไฟฟ้าดูด
- ถ้าไม่สามารถหลีกเลี่ยงการใช้งานเครื่องมือกลในสถานที่ที่มี  
ความเสี่ยงได้ ให้ใช้อุปกรณ์ป้องกันไฟดูด (RCD) ในการป้องกัน  
ใช้อุปกรณ์ป้องกันไฟดูดเพื่อลดความเสี่ยงการเกิดไฟฟ้าช็อต

#### 3) ความปลอดภัยส่วนบุคคล

- ระวังตัว ตู้อื่นที่คุณกำลังทำ ใช้สามัญสำนึกเมื่อใช้เครื่องมือ  
ไฟฟ้า อย่าใช้เครื่องมือไฟฟ้าเมื่อคุณอ่อนแอลงหรือกินยา สุรา  
หรือยาเสพติด  
การขาดสติชั่วขณะเมื่อใช้เครื่องมือไฟฟ้าอาจทำให้คุณบาดเจ็บ  
สาหัส

- ใช้อุปกรณ์ป้องกันส่วนบุคคล สวมแว่นตาป้องกันเสมอ  
อุปกรณ์ป้องกัน เช่น หน้ากากกันฝุ่น รองเท้ากันลื่น หมวกกันน็อก  
หรืออุปกรณ์อุตสาหกรรมที่เหมาะสม จะลดการบาดเจ็บของร่างกายได้
- ป้องกันเครื่องจักรทำงานโดยไม่ตั้งใจ อย่าลืมหักสวิตช์ขอยุใน  
ตำแหน่งปิด ก่อนเสียบไฟและ/หรือต่อกับแบตเตอรี่ ก่อนการ  
เก็บ หรือการเคลื่อนย้ายเครื่องมือ  
เมื่อจับเครื่องมือไฟฟ้าเมื่อนิวอยู่ที่ตัวสวิตช์ หรือเมื่อเสียบปลั๊ก  
ขณะเปิดสวิตช์ไว้อาจทำให้เกิดอุบัติเหตุ
- เอาสลับปรับแต่งหรือประแจออกก่อนเปิดสวิตช์ไฟฟ้า  
สลับหรือประแจที่ติดกับส่วนหมุนของเครื่องมือไฟฟ้าอาจทำให้  
คุณบาดเจ็บได้
- อย่าเอื้อมตัว ยืนให้มั่นและสมดุลตลอดเวลา  
ทำให้ควบคุมเครื่องมือไฟฟ้าได้ดีขึ้นเมื่อมีเหตุที่ไม่คาดฝัน
- แต่งตัวให้รัดกุม อย่าสวมเสื้อผ้าหลวมหรือใช้เครื่องประดับ ให้  
ผม เสื้อผ้าและถุงมืออยู่ห่างจากชิ้นส่วนที่เคลื่อนที่  
เสื้อผ้าหลวม เครื่องประดับหรือผมอาจถูกชิ้นส่วนหมุนรั้ง  
เข้าไป
- ถ้าออกแบบเครื่องมือไฟฟ้าไว้ให้ต่อกับชุดดูดฝุ่นหรือเศษวัสดุ  
ให้เชื่อมต่อและใช้งานอย่างถูกต้อง  
ใช้เครื่องเก็บฝุ่นเพื่อลดฝุ่นผงที่อันตราย

#### 4) การใช้และบำรุงรักษาเครื่องมือไฟฟ้า

- อย่าใช้เครื่องมือไฟฟ้าโดยฝืนกำลัง ใช้เครื่องมือที่ถูกต้องกับ  
งานของคุณ  
เครื่องมือไฟฟ้าที่ถูกต้องจะทำงานได้ดีกว่าและปลอดภัยกว่า ใน  
อัตราตามที่ออกแบบไว้แล้ว
- อย่าใช้เครื่องมือไฟฟ้าถ้าสวิตช์ปิดเปิดไม่ได้  
เครื่องมือไฟฟ้าที่ควบคุมด้วยสวิตช์ที่ไม่ได้จะมีอันตรายและต้อง  
ซ่อมเสีย
- ถอดปลั๊กจากแหล่งไฟฟ้าและ/หรือถอดแบตเตอรี่ออกจากเครื่อง  
มีกอลก่อนทำการปรับแต่งใดๆ เปลี่ยนอุปกรณ์เสริม หรือเก็บ  
รักษา  
มาตรการป้องกันเช่นนี้จะลดความเสี่ยงของอุบัติเหตุที่  
เครื่องมือไฟฟ้าจะเริ่มทำงานโดยไม่ได้ตั้งใจ
- เก็บเครื่องมือไฟฟ้าให้ห่างจากเด็ก และอย่ายอมให้ผู้ที่ไม่เคยชิน  
กับเครื่องมือไฟฟ้าหรือคำแนะนำเหล่านี้ให้ใช้เครื่องมือไฟฟ้า  
เครื่องมือไฟฟ้าเป็นสิ่งที่มีอันตรายมากเมื่ออยู่ในมือของคนที่ไม่  
ชำนาญ
- บำรุงรักษาเครื่องมือไฟฟ้า ตรวจสอบศูนย์เคลื่อน ส่วนบิตของ ชาร์จ  
หรือสภาพอื่นๆ ที่มีผลต่อการทำงานของเครื่องมือไฟฟ้า  
หากชำรุด ให้ซ่อมแซมเสียก่อนใช้งาน  
อุบัติเหตุจำนวนมากเกิดจากเครื่องมือไฟฟ้าที่บำรุงรักษาไม่ดีพอ
- ให้เครื่องมือตัดมีความคมและสะอาด  
เครื่องมือตัดที่บำรุงรักษาอย่างถูกต้องและมีขอบคมจะไม่ค่อย  
บิตงอ และควบคุมได้ง่ายกว่า
- ใช้เครื่องมือกล อุปกรณ์เสริม และเครื่องมือชิ้นเล็กชิ้นน้อย ฯลฯ  
ตามคำแนะนำเหล่านี้ โดยคำนึงถึงสภาพการทำงาน และงานที่  
จะทำ

การใช้เครื่องมือเพื่อทำงานที่แตกต่างไปจากสิ่งที่กำหนดไว้เหล่านี้นั้น อาจก่อให้เกิดอันตรายได้

5) การดูแลรักษาและการใช้แบตเตอรี่

- a) ชาร์จแบตเตอรี่ซ้ำโดยใช้เครื่องชาร์จตามที่ผู้ผลิตกำหนดไว้เท่านั้น  
หากนำเครื่องชาร์จที่เหมาะสมมาใช้ร่วมกับแบตเตอรี่ประเภทอื่นมาใช้กับแบตเตอรี่อีกประเภท อาจทำให้เกิดไฟไหม้ได้
- b) ใช้เครื่องมือที่ต้องการกำลังไฟกับแบตเตอรี่ตามประเภทที่ได้ระบุไว้เท่านั้น  
การใช้แบตเตอรี่แบบอื่นอาจทำให้เกิดไฟไหม้และการบาดเจ็บได้
- c) เมื่อไม่ใช้งานแบตเตอรี่ ควรเก็บให้ห่างจากวัตถุที่เป็นโลหะ เช่น คลิปหนีบกระดาษ เหรียญ กุญแจ ตะปู สกรู หรือวัตถุที่เป็นโลหะขนาดเล็กๆ ที่สามารถเชื่อมต่อขั้วต่อเข้าด้วยกันได้  
การลัดวงจรขั้วต่อแบตเตอรี่เข้าด้วยกันอาจทำให้เกิดแผลไหม้พุพองหรือไฟไหม้ได้
- d) ภายใต้อุณหภูมิที่เป็นอันตราย อาจมีของเหลวรั่วซึมออกจากแบตเตอรี่ ห้ามสัมผัสกับของเหลวดังกล่าว หากสัมผัสกับของเหลวโดยบังเอิญ ให้ล้างออกด้วยน้ำสะอาด หากของเหลวเข้าตา ควรรีบไปพบแพทย์  
ของเหลวที่ไหลออกจากแบตเตอรี่อาจทำให้เกิดอาการระคายเคืองหรือแผลไหม้พุพองได้

6) การซ่อมบำรุง

- a) ให้ช่างซ่อมที่ชำนาญเป็นผู้ซ่อม และเปลี่ยนอะไหล่ที่เป็นของแท้  
ทำให้เครื่องมือไฟฟ้ามีความปลอดภัย

คำเตือน

เก็บให้พ้นมือเด็กและผู้ไม่ชำนาญ

หากไม่ได้ใช้ ควรเก็บให้พ้นมือเด็กและผู้ไม่ชำนาญ

**คำเตือนความปลอดภัยทั่วไปสำหรับงานเจียร์ งานขัด หรืองานตัด**

- a) ออกแบบเครื่องมือไฟฟ้านี้เพื่อใช้กับงานขัดหรืองานตัด โปรดอ่านคำเตือนความปลอดภัย คำแนะนำ ภาพประกอบและรายละเอียดทางเทคนิคที่มีมาพร้อมเครื่องมือนี้  
ถ้าไม่ปฏิบัติตามคำแนะนำข้างล่าง อาจถูกไฟฟ้าดูด ไฟไหม้ และบาดเจ็บสาหัสได้
- b) **ไม่แนะนำให้ใช้เครื่องมือไฟฟ้านี้กับงานตัดกระดาษทราย ขัดแปรงลวด หรืองานขัดเงา**  
หากใช้กับงานอื่นที่ไม่ได้ออกแบบไว้ อาจเกิดความเสียหายและบาดเจ็บสาหัสได้
- c) **อย่าใช้อุปกรณ์ประกอบที่ไม่ได้ออกแบบมาเฉพาะ และผู้ผลิตเครื่องมือไม่ได้แนะนำให้ใช้**  
แม้จะติดอุปกรณ์ประกอบเข้าได้กับเครื่องมือไฟฟ้า ก็อาจไม่สามารถทำงานอย่างปลอดภัยก็ได้
- d) **อย่างน้อยที่สุด พักความเร็วจนอุปกรณ์ประกอบต้องเท่ากับความเร็วสูงสุดที่เขียนไว้บนเครื่องมือไฟฟ้า**  
ถ้าอุปกรณ์ประกอบใช้ความเร็วสูงกว่าพิกัดความเร็ว ก็อาจแตกและปลิวออกได้

- e) เส้นผ่านศูนย์กลางภายนอกและความหนาของอุปกรณ์ประกอบต้อง อยู่ในขีดความสามารถของเครื่องมือไฟฟ้า  
ไม่อาจป้องกันหรือควบคุมอุปกรณ์ประกอบที่ผิดขนาดได้อย่างเพียงพอ
- f) **เกลียวยึดอุปกรณ์เสริมจะต้องตรงกับเกลียวแกนหมุนของเครื่องเจียร์**  
สำหรับอุปกรณ์เสริมที่ติดตั้งแบบยึดเข้ากับหน้าแปลน รูยึดอุปกรณ์เสริมจะต้องสวมพอดีกับเส้นผ่านศูนย์กลางกำหนดตำแหน่งของหน้าแปลน  
อุปกรณ์เสริมที่ไม่ตรงกับอุปกรณ์ยึดของเครื่องมือไฟฟ้า แกนแกว่งออกจากตำแหน่งสมดุล เกิดการสั่นอย่างรุนแรง และอาจส่งผลให้สูญเสียการควบคุมได้
- g) **อย่าใช้อุปกรณ์ประกอบที่ชำรุด** ก่อนการใช้งานแต่ละครั้ง โปรดตรวจสอบอุปกรณ์เสียก่อน เช่น รอยบิ่นหรือร้าวที่หินเจียร์ รอยร้าว รอยฉีกหรือส่วนสึกหรอผิดปกติที่แผ่นทาบหลัง จุดที่หลวมหรือร้าวของแปรงลวด เป็นต้น ถ้าเครื่องมือไฟฟ้าหรืออุปกรณ์ประกอบแตกกระแทก ตรวจสอบความเสียหายหรือเปลี่ยนไปใช้อุปกรณ์ที่ไม่ชำรุด หลังจากตรวจสอบและติดตั้งอุปกรณ์ประกอบแล้ว **หันตัวคุณและคนอื่น ๆ ออกจากระนาบงานหมุนของอุปกรณ์ และเปิดสวิตช์ให้เครื่องมือทำงานโดยไร้แรงกระทำเป็นเวลา 1 นาที**  
ในช่วงที่ทดลองเปิดเครื่องนี้ อุปกรณ์ที่ชำรุดมักแตกออกเป็นชิ้นๆ
- h) **ใช้อุปกรณ์ป้องกันภัยส่วนบุคคล** อาจขึ้นกับลักษณะงาน แต่ควรใช้หน้ากากป้องกัน แวนตานามัย หรือแวนตากล้นฝุ่น ใช้หน้ากากกันฝุ่น จุกปิดหู ถุงมือ และผ้ากันเปื้อนงานช่างตามความจำเป็น เพื่อป้องกันจากเศษวัสดุหรือชิ้นงานที่ปลิวกระเจาย ชูดป้องกันตาต้องสามารถยับยั้งเศษวัสดุที่ปลิวในการปฏิบัติงานต่างๆ ได้ หน้ากากกันฝุ่นหรือชุดช่วยหายใจต้องสามารถกรองอนุภาคเล็ก ๆ จากการทำงานของคุณได้ ถ้าทำงานภายใต้เสียงดังเป็นเวลานาน ความสามารถในการได้ยินอาจสูญเสียไป
- i) **ให้คนอื่น ๆ ยืนห่างจากจุดที่ทำงานจนปลอดภัยเพียงพอ ผู้ที่เข้าไปยังพื้นที่ปฏิบัติงานจะต้องใช้อุปกรณ์ป้องกันภัยส่วนบุคคล**  
เศษของชิ้นงานหรืออุปกรณ์ที่แตกหักอาจกระเด็น และคนที่อยู่ติดกับพื้นที่ปฏิบัติงานอาจบาดเจ็บได้
- j) **จับเครื่องมือไฟฟ้าที่ผิวจับซึ่งเป็นฉนวนเท่านั้น** เมื่อใช้งานโดยที่เครื่องมือตัดอาจแตะกับลวดที่มองไม่เห็น  
การสัมผัสกับลวดที่มี "กระแส" อยู่จะทำให้ชิ้นส่วนโลหะของเครื่องมือไฟฟ้าเกิด "กระแส" ด้วยและอาจทำให้ผู้ใช้งานถูกไฟช็อตได้
- k) **วางสายไฟไม่ให้อยู่ใกล้กับอุปกรณ์หมุน**  
เพราะว่า ถ้าคุณสูญเสียการควบคุม สายไฟอาจขาดหรือตัด และมือหรือแขนของคุณอาจถูกดูดเข้าไปในอุปกรณ์หมุนก็ได้
- l) **อย่าวางเครื่องมือไฟฟ้าลงจนอุปกรณ์ประกอบหยุดทำงานสนิทแล้ว**  
เพราะว่า อุปกรณ์หมุนอาจแตะกับพื้นและคุณสูญเสียการควบคุมของตัวเครื่องมือไฟฟ้าได้
- m) **อย่าให้เครื่องมือไฟฟ้าทำงานเมื่อถือไว้ข้างๆ ตัวคุณ**  
เพราะการแตะกับอุปกรณ์หมุนโดยไม่ตั้งใจอาจดูดเสื้อผ้า ทำให้อุปกรณ์ติดส่วนของร่างกายของคุณได้

- n) ทำความสะอาดช่องระบายอากาศของเครื่องมือไฟฟ้าอย่างสม่ำเสมอ  
พัดลมของมอเตอร์จะดูดฝุ่นเข้าไปสะสมในเครื่องมือ ทำให้ไฟฟ้ารั่วในชิ้นส่วนโลหะได้
- o) อย่าเปิดสวิตช์เครื่องมือไฟฟ้าใกล้วัสดุที่ติดไฟได้  
เพราะประกายไฟอาจทำให้วัสดุเหล่านี้เผาไหม้
- p) อย่าใช้อุปกรณ์ประกอบที่ต้องใช้น้ำยาหล่อเย็น  
เพราะการใช้น้ำหรือน้ำยาหล่อเย็นอื่นๆ อาจทำให้ไฟฟ้ารั่ว หรือไฟดูดก็ได้

## แรงผลักและคำเตือน

แรงผลักเป็นปฏิกิริยาทันทีจากจานหมุน แผ่นทาบหลัง แปรงหรืออุปกรณ์อื่นๆ ที่ติดหรือสะดุด เมื่อติดหรือสะดุด ทำให้อุปกรณ์หมุนหยุดทำงานโดยเร็ว ทำให้เครื่องมือไฟฟ้าที่ขาดการควบคุมเคลื่อนไปในทิศทางตรงกันข้ามกับทิศทางหมุนของอุปกรณ์ ในจุดที่ยึดไว้ ตัวอย่างเช่น ถ้าจานขัดติดหรือสะดุดกับชิ้นงาน ขอบของจานที่อยู่ร่องขัดจะบากผิวของวัสดุ ทำให้จานขัดไหลออกหรือผลักตัวออก จานขัดอาจกระโดดเข้าหา หรือออกจากตัวผู้ปฏิบัติงาน โดยขึ้นกับทิศทางหมุนของจานขณะที่สะดุด ในกรณีนี้ จานขัดหยابก็อาจแตกได้อีกด้วย

แรงผลักเป็นผลของการใช้เครื่องมือไฟฟ้าอย่างไม่ถูกต้องตามลำดับ และ/หรือผิดประเภท หรือผิดเงื่อนไข และอาจเสี่ยงได้โดยใช้ความระมัดระวังตั้งต่อไปนี้

- a) จับเครื่องมือไฟฟ้าให้แน่น วางตำแหน่งที่ถูกต้องของคุณและแขน เพื่อรับกับแรงดันได้พอเพียง ใช้มือถือช่วยถ้ามี เพื่อให้ควบคุมแรงดันหรือแรงบิดได้ดีที่สุดเมื่อเริ่มสวิตช์เปิดเครื่องมือ ผู้ปฏิบัติงานอาจควบคุมแรงบิดหรือแรงดันได้ ถ้าใช้ความระมัดระวังมากพอ
- b) อย่าวางมือของคุณไว้ใกล้อุปกรณ์ที่หมุน  
เพราะอุปกรณ์เช่นนั้นอาจผลักตัวเองมาที่มือของคุณก็ได้
- c) อย่ายืนในตำแหน่งที่เครื่องมือไฟฟ้าอาจผลักตัวมา เมื่อเกิดแรงดันขึ้นมา  
แรงดันจะทำให้เครื่องมือไปยังทิศทางหมุนของจานขัด ในจุดที่สะดุด
- d) ใช้ความระมัดระวังเป็นพิเศษเมื่อทำงานกับมุม ขอบที่คม เป็นต้น  
อย่ากระเด็นหรือตัดอุปกรณ์  
มุม ขอบคมหรือแฉกทำให้จานหมุนสะดุด และสูญเสียการควบคุมหรือเกิดแรงดันได้
- e) อย่าตัดโซ่เลื่อยตัดไม้หรือฟันเลื่อยตัดไม้  
เพราะใบเลื่อยเช่นนั้นมักเกิดแรงดันและสูญเสียการควบคุมได้บ่อย

## คำเตือนความปลอดภัยเฉพาะสำหรับงานเจียร์ งานขัด หรืองานตัด

- a) ใช้เฉพาะงานขัดที่ออกแบบเฉพาะสำหรับเครื่องมือไฟฟ้าของคุณ และใช้แผ่นกั้นเฉพาะงานขัดแต่ละอย่าง  
หากใช้งานขัดที่ไม่ได้ออกแบบไว้ใช้กับเครื่องมือไฟฟ้า อาจป้องกันได้ไม่พอ และขาดความปลอดภัย
- b) ต้องยึดหน้าผิวเจียร์ของหินเจียร์ศูนย์คมให้ต่ำกว่าระนาบของขอบแผ่นกั้น แผ่นงานที่ติดตั้งอย่างไม่เหมาะสม โดยยื่นพ้นจากระนาบขอบแผ่นกั้น จะไม่ได้รับการป้องกันอย่างเพียงพอ
- c) ต้องติดแผ่นกั้นเข้ากับเครื่องมือไฟฟ้าให้แน่น และอยู่ในตำแหน่งที่ปลอดภัยสูงสุด เพื่อให้งานขัดหันเข้าหาผู้ปฏิบัติงานในขั้นสุดท้าย  
แผ่นกั้นจะช่วยป้องกันผู้ปฏิบัติงานจากเศษแผ่นงานที่แตกหัก การสัมผัสกับแผ่นงานโดยไม่ตั้งใจ รวมถึงประกายไฟซึ่งอาจทำให้เสื้อผ้าติดไฟได้
- d) ต้องใช้งานขัดกับงานที่แนะนำไว้เท่านั้น ตัวอย่างเช่น: อย่าขัดด้วยด้านข้างของจานตัดตากเพชร  
เนื่องจากได้ออกแบบงานขัดไว้เพื่องานขัดตามเส้นรอบวงแรงกระทำที่ด้านข้างของจานอาจทำให้สั่นหรือโยกได้
- e) ใช้หน้าแปลนงานขัดที่ไม่ชำรุด มีขนาดและรูปร่างถูกต้องตามงานขัดที่คุณเลือก  
หน้าแปลนที่เหมาะสมจะรองรับงานขัด และลดโอกาสที่งานขัดจะแตกหัก หน้าแปลนของงานขัดอาจต่างจากหน้าแปลนของงานขัดก็ได้
- f) อย่าใช้งานขัดที่สึกหรือกับเครื่องมือไฟฟ้าขนาดใหญ่กว่า  
เพราะงานขัดที่ใช้กับเครื่องมือขนาดใหญ่ไม่เหมาะสมกับเครื่องมือเล็กที่ความเร็วสูงกว่า และอาจแตกกระจายได้

## คำเตือนความปลอดภัยเพิ่มเติม เฉพาะสำหรับงานเจียร์ งานขัด หรืองานตัด

- a) อย่า "แช่" งานตัดหรือที่แรงกดมากเกินไป อย่าพยายามตัดให้เป็นร่องลึกเกินไป  
ถ้าใช้แรงกดมาก งานขัดจะรับแรงสูงขึ้นและมีความเปราะบางมากขึ้น ทำให้งานขัดบิดหรือองในร่องตัดและอาจเกิดแรงผลักหรืองานตัดอาจแตกได้
- b) อย่ายืนอยู่ในเส้นแนวของจาน และอยู่ด้านหลังของจานหมุน  
ในตำแหน่งที่ปฏิบัติงาน งานขัดจะเลื่อนออกจากตัวคุณ และแรงผลักอาจทำให้งานที่กำลังหมุนและตัวเครื่องมือมีวงเข้ามาทางตัวคุณก็ได้
- c) เมื่อจานขัดติดแน่น หรือหยุดติดเนื่องจากสาเหตุใดๆ ให้ปิดสวิตช์เครื่องมือไฟฟ้า และจับไว้หนึ่งๆ จนงานขัดหยุดสนิท อย่าพยายามเอาจานตัดออกจากร่องตัดเมื่อยังมีหมุนอยู่ เพราะอาจเกิดแรงผลักขึ้นได้  
ตรวจหาสาเหตุและแก้ไขสาเหตุที่งานขัดบิดงอเสีย
- d) อย่าเปิดสวิตช์อีกเมื่องานตัดยังอยู่ในชิ้นงาน  
โปรดเปิดสวิตช์จนงานหมุนได้ความเร็วเต็มที่ และนำเข้าไป ที่ร่องตัดอีกครั้ง

## ไทย

เพราะงานตัดอาจอ ดลางขึ้นหรือหลัก ถ้าเปิดสวิทช์เมื่องานตัดยังฝังอยู่ในชิ้นงาน

### e) ยึดแท่งไม้หรือชิ้นงานขนาดใหญ่กว่าปกติให้แน่นเพื่อไม่ให้หินเจียร์ผิดและกระดอนกลับ

ชิ้นงานขนาดใหญ่มักอ่อนเพราะน้ำหนักของตัวเอง ต้องรองรับได้ชิ้นงานใกล้เคียงเส้นของการตัดและกล่องของชิ้นงานทั้งสองด้านของหินเจียร์

### f) ใช้ความระมัดระวังเป็นพิเศษเมื่อตัดให้เป็นรูเข้าไปในผนังหรือส่วนอื่นๆ ที่มองไม่เห็น

หินเจียร์ที่ยื่นออกมาอาจตัดท่อน้ำ หรือแก๊ส สายไฟ หรือวัตถุอื่นๆ ซึ่งอาจทำให้กระดอนกลับได้

- ห้ามลัดวงจรแบตเตอรี่แบบรีชาร์จ
- การลัดวงจรแบตเตอรี่จะทำให้เกิดการสั่นและไฟและความร้อนสูง ซึ่งทำให้แบตเตอรี่ไหม้หรือเสียหายได้
- ห้ามเผาแบตเตอรี่
- หากแบตเตอรี่ไหม้อาจทำให้เกิดการระเบิดได้
- ห้ามใส่วัตถุเข้าไปในช่องระบายอากาศของเครื่องชาร์จ การใส่วัตถุที่เป็นโลหะหรือวัตถุติดไฟได้เข้าไปในช่องระบายอากาศจะทำให้เกิดอันตรายจากไฟฟ้าดูดหรือทำให้ความเสียหายให้เครื่องชาร์จได้
- นำแบตเตอรี่ที่ชื้อมากลับไปยังร้านทันที หากชาร์จแบตเตอรี่และสามารถใช้งานแบตเตอรี่ได้เพียงช่วงสั้นๆ เท่านั้น ห้ามทิ้งแบตเตอรี่ที่คายประจุจนหมดแล้ว

## คำแนะนำเกี่ยวกับความปลอดภัยโดยทั่วไปสำหรับเครื่องเจียร์ไฟฟ้าไร้สาย

- ตรวจสอบว่า รอบหมุนบนงานตัดไม่น้อยกว่ารอบหมุนของเครื่องตัดไฟฟ้า
- โปรดแน่ใจว่า ขนาดของงานตัดเหมาะสมกับเครื่องตัดไฟฟ้า;
- เก็บและใช้งานขัดตามคำแนะนำของผู้ผลิต;
- ตรวจสอบงานขัดก่อนใช้งาน อย่าใช้งานขัดที่แตก ร้าวหรือชำรุด;
- โปรดแน่ใจว่า ได้ติดตั้งงานขัดและลัดไปตามข้อกำหนดของผู้ผลิต;
- โปรดแน่ใจว่า ได้ใช้กระดาษขัด เมื่อแนบมากับงานขัดแบบกาว และเมื่อมีความจำเป็น;
- โปรดแน่ใจว่า ติดตั้งและยึดงานขัดไว้อย่างแน่นหนาก่อนใช้งาน แล้วเปิดเครื่องโดยไม่ได้ขัดในตำแหน่งที่ปลอดภัยประมาณ 30 วินาทีหยุดทันทีถ้ามีการสั่นผิดปกติ หรือตรวจพบความผิดปกติอื่นๆ ถ้าเกิดการกระเด็น ตรวจสอบเช็คเครื่องมือเพื่อหาสาเหตุเสีย;
- ถ้าเครื่องมือมีแผ่นก้ำบังมาด้วย อย่าใช้งานเมื่อถอดแผ่นก้ำบังออกไป;
- เมื่อใช้ลัดตัดและขัดดู ให้แน่ใจว่าได้นำตัวป้องกันลือที่เป็นอุปกรณ์เสริมมาตรฐานออก และตัดตัวป้องกันลือที่ตัวป้องกันด้านข้าง (จำหน่ายแยกต่างหาก) (รูปที่ 5);
- อย่าใช้บูชหรือปลอกแยกเพื่อปรับขนาดงานขัดที่มีรู;
- ถ้าเป็นเครื่องมือที่ออกแบบมาให้ใช้กับงานขัดรูปเกลียว โปรดแน่ใจว่าเกลียวของงานขัดยาวพอที่จะรองรับความยาวของเพลลาได้;
- ตรวจสอบว่า ได้รองรับชิ้นงานไว้แน่นหนาแล้ว;
- อย่าใช้งานตัดเพื่อขัดด้านข้าง;
- โปรดแน่ใจว่า เศษวัสดุจากงานขัดไม่ทำให้เกิดอันตราย เช่นไม่กระเด็นใส่คน หรือทำให้วัสดุหลุดตีไฟ;
- โปรดแน่ใจว่า เปิดช่องระบายอากาศไว้เมื่อทำงานในที่ๆ มีฝุ่นมาก ถ้าจะต้องระบายฝุ่นออก ในตอนแรกให้ถอดออกจากแหล่งจ่ายไฟ (ใช้วัสดุที่เป็นโลหะ) และอย่าทำให้ชิ้นส่วนภายในเสียหาย;
- ใช้อุปกรณ์ป้องกันตาและหูเสมอ ควรใช้อุปกรณ์ป้องกันภัยส่วนบุคคลอื่นๆ ตามที่จำเป็น เช่นหมวกกันน็อค ถุงมือ หมวกกันน็อค และผ้าคาดกันเปื้อน เป็นต้น;
- โปรดสังเกตว่า งานขัดยังหมุนต่อไป แม้ปิดสวิทช์ของเครื่องมือไปแล้วก็ตาม
- อย่าให้วัตถุตกลงปลอมเข้าไปในช่องสำหรับใส่แบตเตอรี่
- ห้ามถอดแยกแบตเตอรี่แบบรีชาร์จและเครื่องชาร์จ

## คำเตือนด้านความปลอดภัยเพิ่มเติม

1. ตรวจสอบให้แน่ใจว่าหินเจียร์ศูนย์จัมที่ใช้งานเป็นชนิดที่ถูกต้องและไม่แตกหรือชำรุดที่พื้นผิว พร้อมตรวจสอบว่าหินเจียร์ศูนย์จัมถูกติดตั้งอย่างถูกต้องและแหวนสกรูขันแน่นเพียงพอ
2. ให้แน่ใจว่าปุ่มกดอยู่ด้วยการกดปุ่มกดสองหรือสามครั้งก่อนกดเปิดเครื่องมือไฟฟ้า
3. เพื่อยืดอายุของเครื่องมือ และทำงานได้คุณภาพที่ดีที่สุด จะต้องไม่ให้เครื่องมือทำงานหนักเกินไปเนื่องจากใช้แรงกดสูง ในงานส่วนใหญ่ น้ำหนักของเครื่องมืออย่างเดียวจะเพียงพอในการเจียร์ให้ได้ผลดี แรงกดมากเกินไปจะลดความเร็วหมุน ผิวชิ้นงานจะเสีย และเกิด แรงมากจนลดอายุใช้งานของเครื่องมือ
4. หินเจียร์จะยังคงหมุนต่อหลังจากปิดเครื่องแล้ว เมื่อปิดสวิทช์ของเครื่องมือ อย่าวางลงจนหินเจียร์หยุดหมุนแล้ว นอกจากจะเสี่ยงอุบัติเหตุร้ายแรงแล้ว ข้อควรระวังนี้ยังจะลดฝุ่นผงที่จะเข้าไปในตัวเครื่องมืออีกด้วย
5. ตรวจสอบออกจากแหล่งจ่ายไฟ ถ้าไม่ได้ใช้งานเครื่องใช้ไฟฟ้าอยู่
6. ก่อนประกอบหรือถอดหินเจียร์ศูนย์จัม จะต้องปิดการทำงานของเครื่องมือและถอดปลั๊กออกจากตัวรับเพื่อหลีกเลี่ยงอุบัติเหตุร้ายแรง
7. ระวังแรงผลักจากเบรก
8. เครื่องเจียร์ไร้สายนี้มีเบรกไฟฟ้าที่ทำงานเมื่อปล่อยสวิทช์ โดยจะมีแรงผลักเล็กน้อยเมื่อเบรกทำงาน โปรดแน่ใจว่าได้ยึดตัวเครื่องมือไว้ อย่างมั่นคง
9. ห้ามใช้งานผลิตภัณฑ์หากเครื่องมือหรือหัวแบตเตอรี่ (แบตเตอรี่เมท) มีการเปลี่ยนรูปร่าง การใส่แบตเตอรี่สามารถทำให้เกิดการลัดวงจรซึ่งส่งผลให้เกิดการปล่อยควันหรือเกิดประกายไฟได้
9. รักษาชีวิตของเครื่องมือ (แบตเตอรี่เมท) ไม่ให้มีเศษไม้หรือเศษโลหะและฝุ่น
  - ก่อนใช้งาน ให้แน่ใจว่าเศษไม้หรือเศษโลหะและฝุ่นไม่สะสมอยู่บริเวณหัวต่อ
  - ระหว่างใช้งาน หลีกเลี่ยงไม่ให้เศษไม้หรือเศษโลหะและฝุ่นจากเครื่องตกลงไปในแบตเตอรี่
  - เมื่อหยุดการทำงานไว้ชั่วคราวหรือหลังใช้งาน ห้ามวางเครื่องมือไว้ในที่ที่เศษไม้หรือเศษโลหะและฝุ่นตกลงไปในแบตเตอรี่ได้ หากเกิดเหตุการณ์ดังกล่าวจะทำให้เกิดการลัดวงจรซึ่งส่งผลให้เกิดการปล่อยควันหรือเกิดประกายไฟได้

## คำเตือนสำหรับแบตเตอรี่และเครื่องชาร์จ

1. ชาร์จแบตเตอรี่ที่อุณหภูมิแวดล้อม -10—40°C ทุกครั้ง หากอุณหภูมิต่ำกว่า -10°C จะทำให้ชาร์จเกินซึ่งก่อให้เกิดอันตรายได้ ไม่สามารถชาร์จแบตเตอรี่ในที่ที่มีอุณหภูมิสูงกว่า 40°C ได้ อุณหภูมิที่เหมาะสมที่สุดในการชาร์จอยู่ที่ 20—25°C
2. ห้ามใช้งานเครื่องชาร์จต่อเนื่อง เมื่อทำการชาร์จครั้งหนึ่งเสร็จสิ้นลง ควรปล่อยเครื่องชาร์จทิ้งไว้ประมาณ 15 นาที ก่อนทำการชาร์จแบตเตอรี่ครั้งต่อไป
3. อย่าให้วัสดุแปลกปลอมเข้าไปในช่องสำหรับใส่แบตเตอรี่
4. ห้ามถอดแยกแบตเตอรี่แบบรีชาร์จ หรือเครื่องชาร์จ
5. ห้ามลัดวงจรแบตเตอรี่แบบรีชาร์จ การลัดวงจรแบตเตอรี่จะทำให้เกิดกระแสไฟและความร้อนสูง ซึ่งทำให้แบตเตอรี่ไหม้หรือเสียหายได้
6. ห้ามเผาแบตเตอรี่ หากแบตเตอรี่ไหม้อาจทำให้เกิดการระเบิดได้
7. การใช้งานแบตเตอรี่ที่คายประจุจนหมดแล้วจะทำให้เครื่องชาร์จเสียหาย
8. นำแบตเตอรี่ที่ซื้อมากลับไปยังร้านทันที หากชาร์จแบตเตอรี่และสามารถใช้งานแบตเตอรี่ได้เพียงช่วงสั้นๆ เท่านั้น ห้ามทิ้งแบตเตอรี่ที่คายประจุจนหมดแล้ว
9. ห้ามใส่วัตถุเข้าไปในช่องระบายอากาศของเครื่องชาร์จ การใส่วัตถุที่เป็นโลหะหรือวัตถุติดไฟได้เข้าไปในช่องระบายอากาศจะทำให้เกิดอันตรายจากไฟฟ้าดูดหรือทำให้ความเสียหายให้เครื่องชาร์จได้

## ข้อควรระวังเกี่ยวกับแบตเตอรี่ลิเทียม-ไอออน

เพื่อยืดอายุการใช้งาน แบตเตอรี่ลิเทียม-ไอออนมีฟังก์ชันการป้องกันเพื่อหยุดการปล่อยพลังงาน

ในกรณีที่เกิดเหตุการณ์ในข้อ 1 ถึง 3 ที่มีการอธิบายด้านล่างในขณะที่ใช้ผลิตภัณฑ์นี้ แม้ว่าคุณจะถูกแจ้งเตือนถึงความเสี่ยง มอเตอร์อาจหยุดหมุน เป็นปัญหาใหญ่ แต่เป็นผลของฟังก์ชันการป้องกัน

1. เมื่อหลังจากที่เหล็อยู่ของแบตเตอรี่หมดไป มอเตอร์จะหยุดหมุนในกรณีดังกล่าว ให้ชาร์จแบตเตอรี่ทันที
2. ถ้าเครื่องมือมีการใช้งานเกินปกติ มอเตอร์อาจหยุดหมุน ในกรณีนี้ ให้ปล่อยสวิตช์ของเครื่องมือ และกำจัดสาเหตุของการทำงานเกินปกติ หลังจากนั้น คุณสามารถใช้เครื่องมือต่อไปได้อีกครั้ง
3. ถ้าแบตเตอรี่ร้อนเกินไปภายใต้การใช้งานปกติ แบตเตอรี่อาจหยุดจ่ายพลังงานในกรณีนี้ ให้หยุดการใช้แบตเตอรี่ และปล่อยให้แบตเตอรี่เย็นลง หลังจากนั้น คุณสามารถใช้เครื่องมือต่อไปได้อีกครั้ง

ยิ่งไปกว่านั้น โปรดใส่ใจถึงคำเตือนและข้อควรระวังต่อไปนี้

### คำเตือน

เพื่อป้องกันการรั่วของแบตเตอรี่ การสร้างความร้อน การปล่อยคลื่น การระเบิด หรือการเกิดประกายไฟ โปรดมั่นใจว่าคุณใส่ใจถึงข้อควรระวังต่อไปนี้

1. ตรวจสอบให้แน่ใจว่า ไม่มีกระแสลมของเศษไม้หรือเศษโลหะและฝุ่นในแบตเตอรี่
- ระหว่างการทำงาน ให้แน่ใจว่าเศษไม้หรือเศษโลหะและฝุ่นไม่ตกลงไปบนแบตเตอรี่
- ตรวจสอบให้แน่ใจว่าเศษไม้หรือเศษโลหะและฝุ่นที่ตกลงไปบนเครื่องมือไฟฟ้า ไม่สะสมบนแบตเตอรี่
- อย่าเก็บแบตเตอรี่ที่ไม่ได้ใช้ในสถานที่ซึ่งสัมผัสถูกเศษไม้หรือเศษโลหะและฝุ่น
- ก่อนที่จะเก็บแบตเตอรี่ ให้ปิดเศษไม้หรือเศษโลหะและฝุ่นที่ติดอยู่ ออก และอย่าเก็บไว้ที่เดียวกับชิ้นส่วนที่เป็นโลหะ (สกรู ตะปู ฯลฯ)
2. อย่าแทงแบตเตอรี่ด้วยวัตถุที่แหลม เช่น ตะปู ดอกด้วยค้อน ยินบน โยน หรือปล่อยให้แบตเตอรี่ถูกกระแทกอย่างรุนแรง
3. อย่าใช้แบตเตอรี่ที่มีลักษณะเสียหาย หรือมีการเปลี่ยนรูปร่าง
4. อย่าใช้แบตเตอรี่โดยใส่ขั้วกับด้าน
5. อย่าเชื่อมต่อเข้ากับเต้าเสียบไฟฟ้า หรือรูเสียบที่จุดบุหรี่ในรถยนต์โดยตรง
6. อย่าใช้แบตเตอรี่สำหรับวัตถุประสงค์ที่นอกเหนือจากที่ระบุ
7. ถ้าการชาร์จแบตเตอรี่ไม่สมบูรณ์ แม้ว่าถึงเวลาการชาร์จที่ระบุแล้ว ให้หยุดการชาร์จแบตเตอรี่ทันที
8. อย่าวาง หรือปล่อยให้แบตเตอรี่สัมผัสอุณหภูมิที่สูง หรือความดันสูง เช่น ในเตาไมโครเวฟ ตู้อบ หรือภาชนะที่มีความดันสูง
9. เมื่อแบตเตอรี่รั่ว หรือได้กลิ่นผิดปกติ ให้เก็บแบตเตอรี่ให้ห่างจากไฟทันที
10. อย่าใช้ในสถานที่ซึ่งมีการสร้างประจุไฟฟ้าสถิตอย่างรุนแรง
11. ถ้าแบตเตอรี่รั่ว มีกลิ่นผิดปกติ เกิดความร้อน เปลี่ยนสี หรือมีรูปร่างเปลี่ยนไป หรือมีลักษณะผิดปกติ ระหว่างการใช้งาน การชาร์จ หรือขณะเก็บ ให้นำออกจากรถบรรทุก หรือเครื่องชาร์จแบตเตอรี่ทันที และหยุดการใช้งาน
12. ห้ามจุ่มแบตเตอรี่หรือให้ของเหลวใดๆ เข้าไปในแบตเตอรี่ ของเหลวแทรกซึมที่นำไปไฟฟ้า เช่น น้ำ สามารถทำให้เกิดไฟไหม้ หรือระเบิดได้ จัดเก็บแบตเตอรี่ในที่เย็นและแห้ง อยู่ห่างจากวัตถุที่ติดไฟได้ง่าย หลีกเลี่ยงที่มีแก๊สที่ก่อมลพิษในอากาศ

### ข้อควรระวัง

1. ถ้าของเหลวที่รั่วจากแบตเตอรี่เข้าตา อย่าขยี้ตา ให้ล้างออกด้วยน้ำสะอาด เช่น น้ำก๊อก และรีบไปพบแพทย์ทันที ถ้าปล่อยทิ้งไว้โดยไม่ได้รับการรักษา ของเหลวอาจทำให้เกิดปัญหาภัยพิบัติดวงตาได้
2. ถ้าของเหลวที่รั่วจากแบตเตอรี่สัมผัสผิวหนังหรือเสื้อผ้า ให้ล้างออกด้วยน้ำสะอาด เช่น น้ำก๊อกทันที มีความเป็นไปได้ที่ของเหลวนี้สามารถทำให้เกิดการระคายเคืองต่อผิวหนัง
3. ถ้าคุณพบสนิม กลิ่นที่ผิดปกติ การร้อนเกินไป การเปลี่ยนสี การเปลี่ยนรูปร่าง และ/หรือสิ่งผิดปกติ ในขณะที่ใช้แบตเตอรี่เป็นครั้งแรก อย่าใช้ และส่งแบตเตอรี่กลับคืนไปยังผู้จำหน่าย หรือตัวแทนจำหน่ายของคุณ

### คำเตือน

หากมีสิ่งแปลกปลอมเข้าสู่กระแสไฟฟ้าที่ขั้วของแบตเตอรี่ลิเทียมไอออน แบตเตอรี่อาจจะช็อต ก่อให้เกิดไฟไหม้ การเก็บแบตเตอรี่ลิเทียมไอออนต้องปฏิบัติตามกฎที่มีในรายละเอียดต่อไปนี้

## ไทย

- ออววางเคสโลหะต่าง ๆ ตะปุ และสายไฟที่เป็นลือกระแสไฟฟ้า เช่นลวดเหล็กและลวดทองแดงในกรณีทีจัคเก็บ
- เพือป้อกันไม่ให้เกิดการช้อต ให้ใส่แบตเตอรืลงในเครืองมือหรือใส่ฝากรอบแบตเตอรือย่างปลอกัยขนมงไม่เห็นระบุบายอากาศ


## เกี่ยวกับการขนส่งแบตเตอรี่ลิเทียม-ไอออน

เมือขนส่งแบตเตอรืลิเทียม-ไอออน โปรดสังเกตตามข้อควรวะวังดังต่อไปนี้

### คำเตือน

แจ้งบริษัททีทำการขนส่งให้ทราบว่ภายในกล่องบรรจุแบตเตอรืลิเทียม-ไอออน ให้ข้อมูลบริษัทเกี่ยวกับการป้อยพลังงาน และปฏิบัติตามคำแนะนำของบริษัขนส่งเมือเตรียมการขนส่ง

- แบตเตอรืลิเทียม-ไอออนทีมีการป้อยพลังงานออกมามากกว่า 100 Wh ถือเป็นสินค้ำอันตรายตามการจำแนกสินค้ำ และต้องมีขัันตอนปฏิบัติเป็นพิเศษ
- สำหรัการขนส่งไปต่างประเทศ คุณต้องปฏิบัติตามกฎหมายสากลและกฎหรือข้อปฏิบัติของประเทศปลายทาง
- หากติดตั้ง BSL36B18 ในเครืองมือไฟฟ้า การป้อยพลังงานจะเกิน 100 Wh และเครืองจะถูกัจัดประเมทเป็นสินค้ำอันตรายสำหรัการจัดประเมทการขนส่ง



## ข้อควรวะวังในการต่ออุปกรณ์ USB (UC18YSL3)

เมือเกิดปัญหาทีไม่คาดคิด ข้อมูลในอุปกรณ์ USB ทีเชื่อมต่อกับผลิตภัณทีนี้อาจเสียวหายหรือสูญหายได้ ตรวจสอบให้แน้ใจว่ได้ทำการสำรองข้อมูลใด ๆ ทีอยู่ในอุปกรณ์ USB ไว้แล้ว ก่อนนำมาใช้งานกับผลิตภัณทีนี้

ฟังระลือว่บริษัทของเราไม่มีส่วนรับผิดชอบใดๆ สำหรัข้อมูลทีบันทึกไว้ในอุปกรณ์ USB ทีได้รับความเสียวหายหรือสูญหาย รวมไปถึงการชำรุดเสียวหายทีอาจเกิดขึ้นกับอุปกรณ์ทีนำมาเชื่อมต่อ

### คำเตือน

- ก่อนใช้งาน ให้ตวรจเช็คสาย USB ทีเชื่อมต่อ เพือหการชำรุดหรือความเสียวหาย การใช้สาย USB ทีชำรุดหรือเสียวหายอาจเป็นสาเหตุให้เกิดควันหรือการระเบิดได้
- เมือไม่ได้ใช้งานผลิตภัณทีนี้ ให้ปิดพอร์ต USB ไว้ด้วยฝากรอบขงฝุนละอองหรือวัสดุอื่ๆ ทีเกาะในพอร์ต USB อาจเป็นสาเหตุให้เกิดควันหรือการระเบิดได้

### หมายเหตุ

- อาจมีการหยุดพักเป็นครั้งควรวะวังหว่งที่ชาร์จ USB ช้ำ

- เมือไม่ได้ชาร์จอุปกรณ์ USB ให้ ถอดอุปกรณ์ USB ออกจากเครืองชาร์จ

การไม่ปฏิบัติตามอาจไม่เพียงลอายุการใช้งานของแบตเตอรืของอุปกรณ์ USB แล้ว แต่อาจยังมีผลทำให้เกือบตีเหตุทีไม่คาดคิดได้

- อาจไม่สามารถชาร์จอุปกรณ์ USB บางตัวได้ เนื่องจากขัันอยู่กับชนิดของอุปกรณ์นั้นๆ

## ชื่อขัันส่วนอะไหล่ (รูปที่ 1—รูปที่ 15)

①	มอเตอร์	⑩	สวิตช์แสดงสถานะระดับ แบตเตอรื
②	แผ่นป้าย	⑪	ไฟแสดงสถานะระดับ แบตเตอรื
③	สลักล็อก	⑫	คันโยก
④	มือจับข้าง	⑬	ประแจหกเหลี่ยม
⑤	ตัวครอบของเกียร์	⑭	เครืองล้งล้อ (E)
⑥	หินเจียร์ศูนย์จยม	⑮	แหวนสกรู
⑦	สลักเกลียวหัวขม หกเหลี่ยม M5	⑯	ประแจ
⑧	แผ่นกำบังล้อ	⑰	มีดว้ป้องกันด้านข้าง
⑨	แผ่นกรอง	⑱	ล้อตัดและขัดถู
⑩	ล็อกสวิตช์	⑲	ก้านล็อก
⑪	สวิตช์	⑳	ไฟแสดงโหมด
⑫	สวิตช์แสดงสถานะโหมด อัคทีในเมตี	㉑	ฝาปิดขาง
⑬	แบตเตอรื	㉒	ช่องเสียบ USB
⑭	ตัวล้อค	㉓	สาย USB
⑮	ไฟแสดงสถานะการชาร์จ		

## สัญลักษณ์

### คำเตือน

สัญลักษณ์ทีใช้กัอุปกรณ์มีดังต่อไปนี้ ตรวจสอบให้แน้ใจว่คุณเข้าใจ ความหมายเป็นอย่างตือก่อนใช้งาน

	G3618DA: เครืองเจียร์ไร้สาย
	เพือลดความเสียวจากการบาดเจ็บ ผู้ใช้จะต้องอ่านคู่มือการใช้งาน
	สวมอุปกรณ์ป้องกันดวงตาทุกครั้ง
V	แรงดันไฟฟ้าพิกัด
n	ความเร็วพิกัด
n <sub>0</sub>	อัตราความเร็วหมุนอิสระ

## รายละเอียดจำเพาะ

## 1. เครื่องมือไฟฟ้า

	รุ่น	G3618DA
แรงดันไฟฟ้า		36 V
พิกัดความเร็ว		5300 / นาที โหมดตัดโน้มนั้: 3200 / นาที
แผ่นงาน	เส้นผ่าศูนย์กลาง นอกของแผ่นงาน	180 มม.
	เส้นผ่าศูนย์กลางรู แผ่นงาน	22.23 มม.
	ความหนาของ แผ่นงาน	6 มม.
ความเร็วรอบนอก		80 ม/วินาที
แบตเตอรี่ที่ใช้งานได้กับ เครื่องมือรุ่นนี้*		BSL36B18
น้ำหนัก		4.7 กก.

\* แบตเตอรี่ที่มีอยู่ (BSL3660/3620/3626, รุ่น BSL18xx, ฯลฯ) และ อะแดปเตอร์ AC/DC (ET36A) ไม่สามารถใช้กับเครื่องมือนี้ได้

## หมายเหตุ

เนื่องจากโครงการวิจัยและพัฒนาอันต่อเนื่องของ HIKOKI รายละเอียดในเรื่องนี้จะไม่มีการแจ้งให้ทราบล่วงหน้า

## การควบคุมอิเล็กทรอนิกส์

- ซอฟต์แวร์ลดแรงตึงที่มีต่อผู้ใช้งานด้วยการจัดการจำนวนการหมุนในช่วงเริ่มต้นใช้งาน
- ฟังก์ชันการเบรกเบรกจะทำงานเมื่อปิดสวิตช์ซึ่งจะหยุดการหมุนของมอเตอร์
- การป้องกันการเกิดความร้อนสูงเกินไปคุณสมบัติการป้องกันนี้จะตัดพลังงานมอเตอร์และหยุดเครื่องมือไฟฟ้าจากการเกิดความร้อนของมอเตอร์สูงเกินไปขณะตัดเมื่อการป้องกันการเกิดความร้อนสูงเกินไปเริ่มทำงาน มอเตอร์จะหยุดทำงานในกรณีนี้ ให้ปล่อยสวิตช์เครื่องมือและปล่อยให้เครื่องมือเย็นลงหลังจากนั้นคุณสามารถใช้งานได้อีกครั้ง
- การป้องกันการใช้งานเครื่องมือหนักคุณสมบัติการป้องกันนี้จะตัดพลังงานมอเตอร์จากการใช้งานที่หนักเกินไปหรือลดความเร็วของการหมุนขณะตัดอย่างชัดเจนเมื่อการป้องกันการใช้งานเครื่องมือหนักเริ่มทำงาน มอเตอร์จะหยุดทำงานในกรณีนี้ ให้ปล่อยสวิตช์เครื่องมือและกำจัดสาเหตุของการใช้งานเครื่องมือหนักหลังจากนั้นคุณสามารถใช้งานได้อีกครั้ง
- ฟังก์ชันป้องกันการเริ่มงานใหม่เมื่อมือยังไม่พร้อมทำงานใหม่เมื่อแบตเตอรี่ติดตั้งอยู่ ฟังก์ชันนี้สามารถยกเลิกได้เมื่อปิดการใช้งานเครื่องมือ

/min	การหมุนหรือรอบการทำงานต่อนาที
	การเปิดเครื่อง
	การปิดเครื่อง
Lock 	ล็อกอยู่ที่ตำแหน่ง “เปิด”
	ถอดแบตเตอรี่
	คำเตือน
	สวิตช์แสดงสถานะแบตเตอรี่ที่เหลือ

## แบตเตอรี่

	ไฟสว่าง ; พลังงานแบตเตอรี่คงเหลือมากกว่า 75%
	ไฟสว่าง ; พลังงานแบตเตอรี่คงเหลือ 50%—75%
	ไฟสว่าง ; พลังงานแบตเตอรี่คงเหลือ 25%—50%
	ไฟสว่าง ; พลังงานแบตเตอรี่คงเหลือน้อยกว่า 25%
	ไฟกระพริบ ; พลังงานแบตเตอรี่เหลือใกล้หมด ทำการรีชาร์จแบตเตอรี่ให้เร็วที่สุด
	ไฟกระพริบ ; ระบบการปล่อยพลังงานชั่วคราวเนื่องจากอุณหภูมิสูง ถอดแบตเตอรี่ออกจากเครื่องมือและปล่อยให้เย็นลง
	ไฟกระพริบ ; ระบบการปล่อยพลังงานชั่วคราวเนื่องจากเกิดความล้มเหลวหรือทำงานผิดปกติ ปัญหาอาจเกิดขึ้นที่แบตเตอรี่กรุณาติดต่อตัวแทนจำหน่ายของคุณ

## อุปกรณ์มาตรฐาน

นอกจากตัวเครื่อง (1 เครื่อง) แล้ว ภายในแพ็คเกจยังประกอบด้วย อุปกรณ์เสริมที่ระบุในหน้า 29 ด้วย

อาจเปลี่ยนแปลงอุปกรณ์มาตรฐานได้โดยไม่ต้องแจ้งล่วงหน้า

## การใช้งาน

- กำจัดคราบหลอและตกแต่งผิวของวัสดุเหล็ก ทองเหลืองและอะลูมิเนียม และชิ้นงานหล่อ
- เจียรระในชิ้นส่วนเชื่อมหรือหน้าตัดที่ตัดด้วยหัวตัดแก๊ส
- การขัดเรซินสังเคราะห์ หินชนวน อีซู หินอ่อน และอื่นๆ

2. แบตเตอรี่

รุ่น	BSL36B18
แรงดันไฟฟ้า	36 V / 18 V (สลับโดยอัตโนมัติ*)
ความจุแบตเตอรี่	4.0 Ah / 8.0 Ah (สลับโดยอัตโนมัติ*)
ผลิตภัณฑ์ไร้สายที่ใช้งานได้**	ผลิตภัณฑ์รุ่นหลายแรงดัน, 18 V
เครื่องชาร์จที่ใช้งานได้	เครื่องชาร์จแบบเคลื่อนสำหรับแบตเตอรี่ลิเธียม-ไอออน

\* ตัวเครื่องมีจะสลับเองโดยอัตโนมัติ

\*\* โปรดอ่านรายละเอียดได้ในแคตตาล็อกทั่วไป

3. เครื่องชาร์จ

รุ่น	UC18YSL3
แรงดันไฟชาร์จ	14.4 V—18 V
น้ำหนัก	0.6 กก.

การชาร์จ

ก่อนการใช้ส่วนไขควง ให้ทำการชาร์จแบตเตอรี่ตั้งนี้

1. เชื่อมต่อสายไฟเครื่องชาร์จกับตัวรับ

เมื่อเชื่อมต่อปลั๊กของเครื่องชาร์จกับตัวรับแล้ว ไฟแสดงสถานะการชาร์จจะกะพริบเป็นสีแดง (ทุก 1 วินาที)

2. ใส่แบตเตอรี่ลงในเครื่องชาร์จ

เสียบแบตเตอรี่เข้าในแท่นชาร์จตามรูปที่ 3 (ในหน้า 2)

3. การชาร์จ

เมื่อใส่แบตเตอรี่ลงในเครื่องชาร์จ ไฟแสดงสถานะการชาร์จจะกะพริบเป็นสีฟ้า

เมื่อแบตเตอรี่ชาร์จเต็มแล้ว ไฟแสดงสถานะการชาร์จจะสว่างเป็นสีเขียว (ดูตารางที่ 1)

(1) ตัวแสดงสถานะไฟแสดงสถานะการชาร์จ

ตัวแสดงสถานะของไฟแสดงสถานะการชาร์จจะแสดงในตารางที่ 1 ตามสภาพของเครื่องชาร์จ หรือแบตเตอรี่ที่สามารถชาร์จใหม่ได้

ตารางที่ 1

สัญลักษณ์ของไฟแสดงสถานะการชาร์จ				
ชาร์จไฟ แสดงสถานะ (สีแดง / สีน้ำเงิน / สีเขียว / สีม่วง)	ก่อนการชาร์จ	กะพริบ (สีแดง)	สว่างเป็นเวลา 0.5 วินาที ไม่สว่างเป็นเวลา 0.5 วินาที (ดับเป็นเวลา 0.5 วินาที)	ต่อเข้ากับแหล่งจ่ายไฟ
	ในขณะชาร์จ	กะพริบ (สีน้ำเงิน)	สว่างเป็นเวลา 0.5 วินาที ไม่สว่างเป็นเวลา 1 วินาที (ดับเป็นเวลา 1 วินาที)	ความจุไฟฟ้าของแบตเตอรี่เหลือน้อยกว่า 50%
		กะพริบ (สีน้ำเงิน)	สว่างเป็นเวลา 1 วินาที ไม่สว่างเป็นเวลา 0.5 วินาที (ดับเป็นเวลา 0.5 วินาที)	ความจุไฟฟ้าของแบตเตอรี่เหลือน้อยกว่า 80%
		สว่าง (สีน้ำเงิน)	สว่างต่อเนื่อง	ความจุไฟฟ้าของแบตเตอรี่เหลือมากกว่า 80%
	การชาร์จสมบูรณ์	สว่าง (สีเขียว)	สว่างต่อเนื่อง	
	สแตนด์บายเนื่องจากร้อนเกินไป	กะพริบ (สีแดง)	สว่างเป็นเวลา 0.3 วินาที ไม่สว่างเป็นเวลา 0.3 วินาที (ดับเป็นเวลา 0.3 วินาที)	แบตเตอรี่ร้อนเกินไป ไม่สามารถชาร์จได้ (การชาร์จจะเริ่มเมื่อแบตเตอรี่เย็นลง)
การชาร์จไม่สามารถทำได้	กะพริบถี่ (สีม่วง)	สว่างเป็นเวลา 0.1 วินาที ไม่สว่างเป็นเวลา 0.1 วินาที (ดับเป็นเวลา 0.1 วินาที)	แบตเตอรี่หรือเครื่องชาร์จทำงานผิดปกติ	

- (2) เกี่ยวกับอุณหภูมิและเวลาชาร์จของแบตเตอรี่แบบชาร์จซ้ำได้  
อุณหภูมิและเวลาการชาร์จจะเป็นค่าที่แสดงในตารางที่ 2

ตารางที่ 2

		เครื่องชาร์จ		UC18YSL3			
แบตเตอรี่	ประเภทของแบตเตอรี่	Li-ion					
	อุณหภูมิซึ่งแบตเตอรี่สามารถชาร์จใหม่ได้	0°C—50°C					
	แรงดันไฟชาร์จ	โวลต์	14.4		18		
	เวลาในการชาร์จโดยประมาณ (ที่ 20°C)	นาฬิกา	รุ่น BSL14xx		รุ่น BSL18xx		รุ่นที่มีโวลต์หลายระดับ
			(4 เซลล์)	(8 เซลล์)	(5 เซลล์)	(10 เซลล์)	(10 เซลล์)
			BSL1415S : 15 BSL1415 : 15 BSL1415X : 15 BSL1420 : 20 BSL1425 : 25 BSL1430C : 30	BSL1430 : 20 BSL1440 : 26 BSL1450 : 32 BSL1460 : 38	BSL1815S : 15 BSL1815 : 15 BSL1815X : 15 BSL1820 : 20 BSL1825 : 25 BSL1830C : 30 BSL1850C : 32	BSL1830 : 20 BSL1840 : 26 BSL1850 : 32 BSL1860 : 38	BSL36A18 : 32 BSL36B18 : 52
USB	แรงดันไฟชาร์จ	V	5				
	กระแสชาร์จประจุ	A	2				

#### หมายเหตุ

เวลาการชาร์จอาจแตกต่างกันไปตามอุณหภูมิแวดล้อมและแรงดันจากแหล่งจ่ายพลังงาน

#### 4. ถอดสายไฟเครื่องชาร์จออกจากเต้าเสียบ

#### 5. จับเครื่องชาร์จให้แน่นแล้วดึงแบตเตอรี่ออก

#### หมายเหตุ

ให้มั่นใจว่าได้ดึงแบตเตอรี่ออกจากเครื่องชาร์จหลังใช้งานและเก็บเรียบร้อยแล้ว

#### เรื่องการปล่อยกระแสไฟฟ้าของแบตเตอรี่ใหม่หรืออื่น ๆ

เนื่องจากสารเคมีภายในแบตเตอรี่ใหม่และแบตเตอรี่ที่ยังไม่ได้ใช้งานเป็นระยะเวลาหนึ่งไม่ได้เริ่มใช้งาน อาจทำให้เกิดการปล่อยกระแสไฟฟ้าค่าเมื่อเริ่มใช้งานครั้งแรกและครั้งที่สอง สถานการณ์นี้จะเกิดขึ้นชั่วคราว และจะกลับมายังค่าปกติโดยเครื่องชาร์จแบตเตอรี่ 2—3 ครั้ง

#### วิธียืดอายุการใช้งานแบตเตอรี่

- ชาร์จแบตเตอรี่ก่อนที่แบตเตอรี่จะหมด  
เมื่อคุณรู้สึกว่าคุณมีไฟอ่อน ให้หยุดใช้งานเครื่องมือและชาร์จแบตเตอรี่ หากใช้งานเครื่องมือต่อเนื่องและทำให้กระแสไฟอ่อนใกล้กับแบตเตอรี่อาจเสียหายและมีอายุการใช้งานสั้นลง
- หลีกเลี่ยงการชาร์จเมื่อมีอุณหภูมิสูง  
แบตเตอรี่ที่ชาร์จได้จะร้อนขึ้นทันทีหลังการใช้งาน หากชาร์จแบตเตอรี่หลังการใช้งานทันที จะทำให้สารเคมีภายในแบตเตอรี่เสื่อมและอายุการใช้งานจะสั้นลง ปล่อยให้แบตเตอรี่เย็นลงสักพักแล้วค่อยชาร์จใหม่

#### ข้อควรระวัง

- หากชาร์จแบตเตอรี่ในขณะที่แบตเตอรี่ร้อน เนื่องจากวางไว้ในสถานที่ที่สัมผัสกับแสงอาทิตย์โดยตรงเป็นเวลานาน หรือเพิ่งใช้งานแบตเตอรี่ ไฟแสดงสถานะการชาร์จของเครื่องชาร์จจะสว่างเป็นเวลา 0.3 วินาที และจะไม่สว่างเป็นเวลา 0.3 วินาที (ดับเป็นเวลา 0.3 วินาที) ในกรณีดังกล่าว ให้แบตเตอรี่เย็นลงก่อน จากนั้นจึงเริ่มชาร์จ
- เมื่อไฟแสดงสถานะการชาร์จจะพริบ (ในระหว่าง 0.2 วินาที) ตรวจสอบและนำสิ่งแปลกปลอมในช่องต่อแบตเตอรี่ของเครื่องชาร์จออก หากไม่มีวัตถุแปลกปลอม เป็นไปได้ว่าแบตเตอรี่หรือแท่นชาร์จทำงานผิดพลาด นำส่งศูนย์ให้บริการที่ได้รับอนุญาต
- เนื่องจากคอมพิวเตอร์ขนาดเล็กในตัวใช้เวลา 3 วินาที ในการยืนยันว่าแบตเตอรี่ที่ชาร์จกับ UC18YSL3 ถูกนำออกแล้ว ให้รออย่างน้อย 3 วินาที ก่อนใส่กลับเข้าไปชาร์จ หากใส่แบตเตอรี่ภายใน 3 วินาที แบตเตอรี่อาจจะไม่ได้ชาร์จ

## การติดตั้งและการใช้งาน

การดำเนินการ	รูป	หน้า
การถอดและการใส่แบตเตอรี่	2	2
การชาร์จ	3	2
ไฟแสดงระดับแบตเตอรี่ที่เหลือ	4	2
การติดตั้งและการปรับแก้ก้านบังหินเจียร์	5	2
การยึดมือจับข้าง	6	3
การประกอบหินเจียร์ศูนย์จัม <sup>*1</sup>	7	3
การประกอบแผ่นงานตัด <sup>*1</sup>	8	3
การใช้งานสวิตช์	9-a	4
การใช้งานสวิตช์ (แบบมีล็อก) <sup>*2</sup>	9-b	4
ปรับจำนวนรอบการหมุน <sup>*3</sup>	10	4
มุมการเจียร์และวิธีการเจียร์	11	4
การถอดแผ่นกรอง	12	5
การชาร์จอุปกรณ์ USB จากตัวรับไฟฟ้า	13-a	5
การชาร์จอุปกรณ์ USB และแบตเตอรี่จากตัวรับไฟฟ้า	13-b	5
วิธีการรีเซ็ตอุปกรณ์ USB	14	5
เมื่อชาร์จอุปกรณ์ USB เสร็จสิ้น	15	5
การเลือกอุปกรณ์เสริม	—	30

**\*1 คำเตือน**

ก่อนใช้งาน ให้ขันแหวนสลักให้แน่นด้วยประแจที่ให้มา หากขันไม่แน่นอาจส่งผลแหวนสลักหลวมเมื่อเบรกทำงานในขณะหยุด

**หมายเหตุ**

เครื่องล้างล้อสำหรับสินค้าโดยเฉพาะ ห้ามใช้กับสินค้าอื่น ๆ

**\*2** อาจมีการเปลี่ยนแปลงขึ้นอยู่กับพื้นที่

**\*3 เกี่ยวกับฟังก์ชันการเปลี่ยนโหมดและไฟแสดงโหมด**

เมื่อติดตั้งแบตเตอรี่แบบชาร์จไฟได้เข้ากับตัวเครื่องและเครื่องเปิดการกดสวิตช์เปลี่ยนโหมดจะสลับโหมดการทำงานเป็นโหมดอัตโนมัติ ขณะอยู่ในโหมดอัตโนมัติ ไฟแสดงโหมดจะยังคงสว่างอยู่

- ในโหมดอัตโนมัติ คุณสามารถลดเสียงรบกวนและการสั่นสะเทือนได้โดยการลดจำนวนรอบการหมุนสูงสุดในขณะที่อยู่ในสถานะไร้แรงกระทำ
- ขณะอยู่ในโหมดอัตโนมัติ จำนวนรอบการหมุนจะเพิ่มขึ้นหากแรงกระทำมากขึ้นระหว่างการทำงาน
- ในทางกลับกัน จำนวนรอบการหมุนจะน้อยลงหากแรงกระทำลดลงระหว่างการทำงาน

- ผลิตภัณฑ์นี้มีฟังก์ชันการป้องกันเมื่อใช้งานฟังก์ชันการป้องกันที่กล่าวถึงด้านล่าง ไฟแสดงโหมดจะกะพริบ

[ฟังก์ชันการป้องกันการใช้งานเครื่องหนัก]

การทำงานจะหยุดเนื่องจากมีการใช้งานเครื่องหนักเกินไป ลองใช้งานเครื่องอีกครั้งเมื่อนำสิ่งที่ทำให้เกิดการใช้งานเครื่องหนักออกไปแล้ว

[ฟังก์ชันป้องกันอุณหภูมิ]

การทำงานจะหยุดเนื่องจากเครื่องร้อนเกินไป ปลดปล่อยเครื่องเย็นลงในตำแหน่งที่มีร่มเงาและมีอากาศถ่ายเทสะดวก

ลองใช้งานเครื่องอีกครั้งหลังจากที่เครื่องเย็นลงพอสมควรแล้ว

## การบำรุงรักษาและการตรวจสอบ

**1. การตรวจสอบหินเจียร์ศูนย์จัม**

โปรดแน่ใจว่า หินเจียร์ศูนย์จัมไม่มีรอยร้าวและรอยบิ่นที่ผิว

**2. การตรวจสอบสกรูยึด**

ให้ตรวจสอบสกรูยึดเสมอ และให้ขันไว้อย่างถูกต้อง ถ้าสกรูหลวม ให้ขันเสียใหม่โดยทันที มิฉะนั้นอาจเกิดอันตรายมาก

**3. การบำรุงรักษามอเตอร์**

การขจัดลวดของมอเตอร์ เป็นหัวใจสำคัญของเครื่องมือไฟฟ้า ให้ใช้ความระมัดระวังเพื่อไม่ให้ขจัดลวดของมอเตอร์ชำรุดและ/หรือเปียกน้ำหรือน้ำมัน

**4. การตรวจสอบข้อต่อ (เครื่องมือและแบตเตอรี่)**

ตรวจสอบให้แน่ใจว่าไม่มีการสะสมของเศษไม้หรือเศษโลหะและฝุ่นในข้อต่อ

การตรวจสอบก่อน ระหว่าง และหลังการทำงานตามโอกาส

**ข้อควรระวัง**

นำเอาเศษไม้หรือเศษโลหะและฝุ่นที่อาจสะสมในข้อต่อได้ออก มิฉะนั้นอาจทำให้เกิดการทำงานผิดปกติได้

**5. การทำความสะอาดภายนอก**

เมื่อจานขัดไร้สายสกปรก ให้เช็ดออกด้วยผ้านุ่มแห้งหรือผ้าชุบน้ำสบู่มหาดๆ ห้ามใช้ตัวทำละลายคลอรีน น้ำมัน หรือทินเนอร์ เนื่องจากสารเหล่านี้จะทำให้พลาสติกละลาย

**6. การทำความสะอาดแผ่นกรอง**

หลังการใช้งาน ให้นำสิ่งสกปรกหรือฝุ่นออกจากแผ่นกรองด้วยปืนเป่าลมหรือเครื่องมืออื่น ๆ (รูปที่ 12)

**หมายเหตุ**

- ในการนำสิ่งสกปรกหรือฝุ่นออกจากเครื่อง ให้ใช้มอเตอร์เป็นระยะในสภาวะไม่มีแรงกระทำและเป่าลมแห้งเข้าไปในช่องระบายอากาศในขณะถอดแผ่นกรองออก
- การสะสมของสิ่งสกปรกหรือฝุ่นที่สะสมในมอเตอร์อาจทำให้เกิดความเสียหายได้
- หลังจากทำความสะอาด ตรวจสอบให้แน่ใจว่าได้ติดตั้งแผ่นกรองอย่างแน่นหนา
- 7. การจัดเก็บ**
- จัดเก็บจานขัดไร้สายในสถานที่ที่อุณหภูมิต่ำกว่า 40°C และเก็บให้พ้นมือเด็ก

**หมายเหตุ**

การจัดเก็บแบตเตอรี่ลิเธียม-ไอออน  
แบตเตอรี่ลิเธียม-ไอออนจะต้องชาร์จไฟเต็มก่อนจัดเก็บ  
การเก็บรักษาแบตเตอรี่ต่อเนื่อง (3 เดือนหรือมากกว่า) ด้วยพลังงาน  
ต่ำอาจทำให้ประสิทธิภาพการทำงานลดลง โดยเฉพาะการลดอายุ  
การใช้งานแบตเตอรี่ หรือทำให้แบตเตอรี่ไม่สามารถเก็บพลังงานไว้  
ได้  
ทั้งนี้สามารถแก้ไขปัญหาเมื่อเวลาใช้งานแบตเตอรี่ลดลงอย่างเห็นได้  
ชัดได้โดยการชาร์จไฟและใช้งานแบตเตอรี่ซ้ำ ๆ กันสองถึงห้ารอบ  
หากเวลาใช้งานแบตเตอรี่สั้นลงมากแม้ว่าจะมีการชาร์จและใช้งาน  
ซ้ำหลายรอบแล้ว แสดงว่าแบตเตอรี่หมดสภาพแล้วและต้องจัดซื้อ  
แบตเตอรี่ใหม่

**ข้อสังเกตที่สำคัญเกี่ยวกับแบตเตอรี่สำหรับเครื่องมือไฟฟ้าไร้สายของ****HIKOKI**

โปรดใช้แบตเตอรี่ของแท่งที่เรากำหนดไว้เสมอ เราไม่สามารถรับประกันความปลอดภัยและสมรรถนะของเครื่องมือไฟฟ้าไร้สายของเราได้ เมื่อใช้กับแบตเตอรี่ที่นอกเหนือจากที่เรากำหนดไว้ หรือเมื่อแบตเตอรี่ถูกถอดชิ้นส่วนหรือมีการดัดแปลง (เช่น การถอดชิ้นส่วนและทดแทนเซลล์แบตเตอรี่ หรือชิ้นส่วนภายใน)

**ข้อควรระวัง**

ต้องปฏิบัติตามระเบียบและมาตรฐานความปลอดภัยของแต่ละประเทศในการใช้งานและบำรุงรักษาเครื่องมือไฟฟ้า

**หมายเหตุ**

เนื่องจาก HIKOKI มีแผนงานวิจัยและพัฒนาอย่างต่อเนื่อง รายละเอียดจำหน่ายนี้อาจเปลี่ยนแปลงได้โดยไม่ต้องแจ้งล่วงหน้า

**การแก้ไขปัญหา**

ใช้การตรวจสอบในตารางด้านล่าง ถ้าเครื่องมือไม่ทำงานเป็นปกติ ถ้าการดำเนินการไม่ได้เป็นการแก้ปัญหา ให้ปรึกษาตัวแทนจำหน่ายของคุณ หรือศูนย์บริการที่ได้รับอนุญาตของ HIKOKI


## 1. เครื่องมือไฟฟ้า


อาการ	สาเหตุที่เป็นไปได้	การแก้ไข
เครื่องมือไม่ทำงาน	ไม่มีพลังงานแบตเตอรี่คงเหลือ	ชาร์จแบตเตอรี่
	ติดตั้งแบตเตอรี่ไม่สมบูรณ์	ถอดแบตเตอรี่ลงไปจนได้ยินเสียงคลิก
	สิ่งแปลกปลอมจะทำให้สลักล็อกค้าง	นำสิ่งแปลกปลอมออกจากสลักล็อก
	ติดตั้งแบตเตอรี่ขณะสวิตช์เปิด	ปิดสวิตช์และเปิดใหม่อีกครั้ง
เครื่องมือหยุดทำงานทันที	เครื่องมือทำงานมากเกินไป	กำจัดปัญหาที่เป็นสาเหตุของการทำงานมากเกินไป
	การป้องกันการใช้งานเครื่องหนักกำลังทำงาน	
	แบตเตอรี่ความร้อนสูง	ปล่อยให้แบตเตอรี่เย็นลง
เสียงดังผิดปกติ งานขัดสั้น	แหวนสกรูหลวม	ขันแหวนสกรูให้แน่น
	แหวนสกรู เครื่องล่าง ล้อ งานขัด หรืออื่น ๆ ติดตั้งผิดพลาด	ตรวจสอบทิศทางที่ติดตั้งและติดตั้งให้ถูกต้อง
	สิ่งแปลกปลอมเข้าไปติดระหว่างแหวนสกรู เครื่องล่าง ล้อ งานขัด หรืออื่น ๆ	นำวัตถุแปลกปลอมออก
เบรกทำงานผิดปกติ	ตัวเครื่องอาจผิดปกติ	หยุดใช้ทันทีและติดต่อตัวแทนจำหน่ายของคุณเพื่อทำการซ่อมแซม
ไม่สามารถใส่แบตเตอรี่ได้	พยายามใส่แบตเตอรี่ในที่ที่นอกเหนือจากที่ระบุไว้สำหรับเครื่องมือ	กรุณาใส่แบตเตอรี่ชนิดที่มีโวลต์หลายระดับ

# ไทย


## 2. เครื่องชาร์จ

อาการ	สาเหตุที่เป็นไปได้	การแก้ไข
ไฟแสดงการชาร์จกระพริบสีม่วงอย่างรวดเร็ว และแบตเตอรี่จะไม่เริ่มชาร์จ	แบตเตอรี่ไม่ได้ใส่อย่างถูกต้อง	ใส่แบตเตอรี่ให้แน่นหนา
	มีวัตถุแปลกปลอมในช่องแบตเตอรี่ หรือที่ใส่แบตเตอรี่	นำวัตถุแปลกปลอมออก
ไฟแสดงการชาร์จกระพริบสีแดง และแบตเตอรี่จะไม่เริ่มชาร์จ	แบตเตอรี่ไม่ได้ใส่อย่างถูกต้อง	ใส่แบตเตอรี่ให้แน่นหนา
	แบตเตอรี่ความร้อนสูง	หากปล่อยให้เย็น แบตเตอรี่จะเริ่มชาร์จอัตโนมัติหากอุณหภูมิลดลง แต่ลักษณะเช่นนี้อาจลดอายุการใช้งานของแบตเตอรี่ด้วย แนะนำว่าทำให้แบตเตอรี่เย็นในพื้นที่ที่ระบายอากาศได้ดี พ้นจากแสงแดดโดยตรงก่อนทำการชาร์จ
เวลาการใช้งานแบตเตอรี่จะสั้นลง แม้ว่า จะชาร์จแบตเตอรี่จนเต็ม	อายุการใช้งานของแบตเตอรี่ลดลง	เปลี่ยนแบตเตอรี่อันใหม่
แบตเตอรี่ใช้เวลานานในการชาร์จ	อุณหภูมิของแบตเตอรี่ เครื่องชาร์จ หรือสภาพแวดล้อมโดยรอบต่ำมาก	ชาร์จแบตเตอรี่ในอาคารหรือในสภาพแวดล้อมอื่นที่อบอุ่นขึ้น
	ช่องระบายอากาศของเครื่องชาร์จอุดตัน ทำให้อุณหภูมิภายในร้อนเกิน	หลีกเลี่ยงการอุดตันของช่องระบายอากาศ
	พัดลมทำความเย็นไม่ทำงาน	ติดต่อศูนย์บริการที่ได้รับอนุญาตของ HIKOKI เพื่อทำการซ่อมแซม
ไฟ USB ปิดและอุปกรณ์ USB จะหยุดชาร์จ	ความจุไฟฟ้าของแบตเตอรี่อยู่ในระดับต่ำ	เปลี่ยนแบตเตอรี่เป็นตัวที่มีความจุไฟฟ้าเหลืออยู่
		เสียบปลั๊กเครื่องชาร์จเข้ากับเต้ารับไฟฟ้า
ไฟ USB ไม่ได้ปิดแม้ว่าอุปกรณ์ USB จะทำการชาร์จเสร็จแล้วก็ตาม	ไฟ USB สว่างเป็นสีเขียวเพื่อระบุว่าสามารถทำการชาร์จ USB ได้	ข้อนี้ไม่ใช่การทำงานผิดปกติ
ไม่แน่ใจว่าสถานะการชาร์จของอุปกรณ์ USB คืออะไร หรือการชาร์จนั้นเสร็จสิ้นแล้วหรือไม่	ไฟ USB ไม่ได้ปิดแม้เมื่อการชาร์จนั้นเสร็จสิ้นแล้วก็ตาม	ตรวจสอบอุปกรณ์ USB ที่กำลังชาร์จเพื่อยืนยันสถานะการชาร์จ
การชาร์จอุปกรณ์ USB ระดับกลางคืน	เสียบเครื่องชาร์จเข้ากับเต้ารับไฟฟ้าขณะกำลังชาร์จอุปกรณ์ USB โดยใช้แบตเตอรี่เป็นแหล่งจ่ายไฟ	ข้อนี้ไม่ใช่การทำงานผิดปกติ
	เสียบแบตเตอรี่เข้าไปในเครื่องชาร์จขณะกำลังชาร์จอุปกรณ์ USB โดยใช้เต้ารับไฟฟ้าเป็นแหล่งจ่ายไฟ	เครื่องชาร์จจะจัดการชาร์จของ USB เป็นเวลาประมาณ 5 วินาที เมื่อแหล่งจ่ายไฟมีความแตกต่างกัน
การชาร์จอุปกรณ์ USB ระดับกลางคืนเมื่อกำลังชาร์จแบตเตอรี่และอุปกรณ์ USB พร้อมกัน	แบตเตอรี่ชาร์จไฟเต็มแล้ว	ข้อนี้ไม่ใช่การทำงานผิดปกติ
		เครื่องชาร์จจะจัดการชาร์จของ USB เป็นเวลาประมาณ 5 วินาที เพื่อตรวจสอบว่าแบตเตอรี่ทำการชาร์จเสร็จสิ้นแล้วหรือไม่
จะไม่เริ่มการชาร์จอุปกรณ์ USB ขณะกำลังชาร์จแบตเตอรี่และอุปกรณ์ USB พร้อมกัน	ประจุไฟฟ้าของแบตเตอรี่คงเหลือต่ำมาก	ข้อนี้ไม่ใช่การทำงานผิดปกติ
		เมื่อความจุไฟฟ้าของแบตเตอรี่ถึงระดับระดับหนึ่ง จะเริ่มทำการชาร์จ USB อัตโนมัติ

	G3618DA	
	(2WC)	(NN)
	1	1
	1	1
	1	1
	2 (BSL36B18)	-
	1	-
	1	1
	2	-



180 mm : 377963




325491



374314




336865



180 mm : 316824 (A24R)




373779




180 mm : 376506




BSL36B18



UC18YSL3  
(14.4 V-18 V)



374409



329897



# Koki Holdings Co., Ltd.

Shinagawa Intercity Tower A, 15-1, Konan 2-chome,  
Minato-ku, Tokyo, Japan